

Date: 03/27/2024

To: **Donnie Bentley**
Dan Ryan Builders
3000 RDU Center Drive
Morrisville, NC 27560
dbentley@drbgroup.com
919-328-0457

Re: **I-Joist Layout Issue**
Location: Lot 4 Honeycutt Hills (69 Shelby Meadown Ln. (Angier, NC))
JDS Project No.: RDU2403203
Date of Inspection: 03/26/2024

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

Observations

A client requested an evaluation of the I joist layout for the first floor. The layout was not per the structural plans provided, but follow the truss layout provided by the manufacturer.

Recommendations

Based on our observations and review, the truss layout is per the manufacturer’s specifications, no repairs are required.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 980-240-5681.

Respectfully Submitted,
Elisha Harris



Reviewing Engineer: Uchenna Onwuemene, PE

