



March 18, 2024

Chuck Michno
David Weekley Homes
1901 Harrison Avenue, Suite 200
Cary, NC 27513
Email: cmichno@dwhomes.com

Reference: Engineering Services
Permit # SFD2401-0047
Serenity - Lot 125
369 Serenity Walk Parkway
Fuquay-Varina, NC 27526
TE&D Project No.: 2401-020118_A

To Whom It May Concern;

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following items:

1. Inspect and analyze the damaged roof truss bearing at the rear wall.

The following conclusions and recommendations were noted:

1. Truss A03 (2nd from the right wall) was damaged at the rear bearing end. The truss was repaired with a 2 x 4 x 6'-0" scab fastened with (2) rows of 10d nails at approximately 4" o.c. Based on our observations and analysis, the repaired truss will provide the required support for the anticipated loading conditions.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,
Tyndall Engineering & Design

Tripp Amos
TA | 2401-020118_A

Prentice Tyndall Jr., P.E.



