

LILLINGTON,NC 27546 Phone: Fax:

10/25/2024

SUBJECT: SFD2402-0036 SINGLE FAMILY DWELLING

To: John Craig

Here are the results of all Inspections located at 2402 SOUTH RIVER RD:

Inspection Type: GAS PIPING Scheduled Date/Time: Completed Date/Time: Inspector: Steven Gazlay Result: Remarks: Notes:

Inspection Type:	INSULATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	OPEN FLOOR
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	SEWER CONNECTION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	TEMP POWER CERTIFICATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	WATER CONNECTION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	ENVIR OPERATIONS PERMIT
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	EH Bucket
Result:	
Remarks:	
Notes:	

Inspection Type:	FINAL SFD CRAWL**
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	FOUNDATION SURVEY
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	CP Bucket
Result:	
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	ROUGH IN REINSPECT Steven Gazlay
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	

Inspector JRM changed the inspection assignment from JRM to TSG

Note: non code compliant structure attached will require an engineer to address .



LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	ROL
Scheduled Date/Time:	10/
Completed Date/Time:	10/
Inspector:	Joh
Result:	DIS
Remarks:	
Notes:	1. F
	Sma

ROUGH IN 10/25/2024 10/25/2024 John B Kokoszka DISAPPROVED

1. Front left window header left of front door not bearing solid 2. Missing shower pan test3. Smoke detector needs to be 12" from the peak 4. DWV is low 5. Need to protect duct return 6. Need fire block fire place chase7. Need to strap 4 stud column behind bathtubNote. Kitchen plumbing has not been completed yet informed going to finish when cabinet gets installed Note: window flashing was covered at the time of inspection

