

April 8th, 2024

Daniel Johnson  
40892 Boyer Ave  
New Market, MD 21774

**Re: Status of Permit Application-SFD2403-0089**

**Mr. Johnson,**

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

**1. Use pink flags to mark property lines and irons that are Set by surveyor need to be visible. (\$25.00 Fee incurred)**

**2. House Box needs to be marked to match site plan (\$25.00 Fee Incurred)**

3. Directions not clear to property (*\$25.00 fee incurred*)

4. Property needs undergrowth cleared, do not disturb the soil

5. Driveway not shown on site plan

6. Backhoe pits required

**7. Other – Optional mark proposed septic and well area and we will try to accommodate the best we can when designing the septic system and well placement.**

Your application will be put on hold until the selected items above have been addressed.

When completed **please call 910-893-7525 ext. 2 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Reynold Levocz R.E.H.S.  
Environmental Health Specialist  
Harnett County Department of Public Health

RL/kh

Copy: Central Permitting