

May 9th, 2024

Jose Morales
105 Otis Way
Holly Springs, NC 27540

Re: Status of Permit Application-SFD2404-0090

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Use pink flags to mark property lines flagged every 50' and irons that are set by surveyor need to be visible. (\$25.00 Fee incurred)
- 2. House Box needs to be marked to match site plan (\$25.00 Fee Incurred)
- 3. Directions not clear to property (\$25.00 fee incurred)
- 4. Property needs undergrowth cleared, do not disturb the soil
- 5. Driveway not shown on site plan

6. Backhoe Pits Required-(48' deep and wide enough to get down into) Must have a step to get out of pit. Contact Environmental Health when planning to have pits dug we can schedule accordingly to avoid weather complications.

7. Other –

Your application will be put on hold until the selected items above have been addressed.

When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Reynold Levocz R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

RL/kh
Copy: Central Permitting