

D.B. 1389, Pg. 248

PIN 9577-84-3949

392.13'

ISS 30.00

S 87°20'53"W (422.13' total)

PKS

1.845 Ac. Total

Rosalva Landaverde, et al

D.B. 1579, Pg. 917

PIN 9577-84-3855

EIS 30.00

390.76'

S 87°19'40"W (420.76' total)

90.76'

PKS

30.00'

EPK

70.00'

EPK

2

Map # 99-233

389.96'

S 87°19'40"W (419.96' total)

EIP 30.00

60' R/W (Hoover Road)

43'11"E (305.76' total)

03°22'21"W (305.94' total)

.01'

ISS

90.92'

ISS


30.00'

EIS

70.01'

EIP

lots 5-9



25'

26'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'

4.88'