





System:   
 Repair: 

System: Gravity to Serial Dist. Lines: 2,3, (315') Accepted Status System 0.35 Soil LTAR 14" Trench Bottom At-Grade
Repair: Pressure Manifold Lines: 1,4-6, (305') Accepted Status System 0.35 Soil LTAR 14" Trench Bottom At-Grade

- \*Keep tanks and drain lines 10' from property lines.
- \*Not a survey.
- \*Not a guarantee of a septic permit.
- \*Keep supply lines >5' from property lines.
- \*Some lines are flagged longer in the field than lengths indicate.
- \*No grading septic area.



Central Carolina Soil Consulting, PLLC  
 1900 South Main Street, Suite 110  
 Wake Forest, North Carolina 27587  
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout  
 with an Engineered Flow Red  
 Lot 179, Birchwood Subdivision  
 Harnett County, North Carolina

Job# : 3753
Drawn By : LW
Date : 04/15/2023
Revision: 06/03/2024