


System:
 Repair:

System: Gravity to Serial Dist.
 Lines: 2-6, (520')
 Accepted Status System
 0.3 Soil LTAR
 22" Trench Bottom

Repair: Pressure Manifold
 Lines: 1 & 7-10 (400')
 T&J Panel
 0.3 Soil LTAR

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

5-Bedroom Septic Layout
 Lot 32, Birchwood Grove Subdivision
 Harnett County, North Carolina

| |
|-------------------|
| Job# : 3753 |
| Drawn By : LW |
| Date : 01/09/2024 |
| Revision: |
| |
| |