

**Date:** 04/18/2025

**To:** **Donnie Bentley**  
Dan Ryan Builders  
3000 RDU Center Drive  
Morrisville, NC 27560  
dbentley@drbgroup.com  
919-328-0457

**Re:** **Notched Roof Trusses**  
Location: Lot 8 Honeycutt Hills (Angier, NC)  
JDS Project No.: RDU2504070  
Date of Inspection: 04/17/2025

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

#### **Observations**

At the attic access door frame at the right rear bedroom access to the rear attic, the installation has notched the vertical webs of the (2) adjacent trusses by as much as 1-1/2" at the top and bottom of the door frame.

#### **Recommendations**

Based on our onsite observations and review, at each of the (2) damaged web members install an 8' long 2x4 scab to each face of the web, beginning at the bottom of the bottom chord and attached with (2) rows of 10d nails at 4" o.c.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 984-297-5949.

Respectfully Submitted,  
John Lowrance



Reviewing Engineer:  
Kyle Edwards, PE, CWI

