

www.tyndallengineering.com

January 10, 2025

Jay Carroll Ascot Homes 540 SW Broad St. Southern Pines, NC 28388 Email: jay@ascotgrp.com

Reference: Engineering Services Permit #SFD2410-0028 171 Travelers Way Lillington, NC 27546 TE&D Project No.: 2501-020023

ENGINEERING & DESIGN, P.A.

To Whom It May Concern:

As requested, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following item(s):

1) Missing foundation projection at the interior face of the front end of the right foundation wall.

The following conclusions and recommendations were noted:

1) Based on our observations and analysis, the projection ranged from 0" to 2" with the majority of the area close to 2". We recommend the footing be uncovered to fully verify. Should the projection be less than 2", the footing is to be repaired with (1) of the following options per the attached details. Upon completion, the newly added section of concrete will provide the required support for the anticipated loading conditions.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely, Tyndall Engineering & Design

if Anos

Tripp Amos TA | 2501-020023






τ 919 773-1200 = ε 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com










## Approximate Location. Extends from step down (3/4 of way from rear wall) to front wall.





Excavate 8" wide trench to match footing depth and install #4 x 8" rebar dowels @ 8" o.c. Embed rebar 4" w/ epoxy