543 Pylon Dr Raleigh, NC 27606 (919) 480-1075 info@idsconsulting.net

jdsconsulting.net

Date: 05/07/2025

To: AJ Napier

Builders First Source - Fayetteville

1135 Robeson Street Fayetteville, NC 28305 andrew.napier@bldr.com

910-322-9690

Re: Truss Issue

Location: 227 Travelers Way Lillington, NC

JDS Project No.: RDU2504776 Date of Inspection: 05/07/25

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

Observations


The client requests an evaluation of the 2x10 that spans over the front porch in front of the front door that (2) D1 roof trusses ledger on to. The 2x10 is toe nailed with approximately (5) nails into stud columns that support the LVL that spans above the 2x10.

Recommendations

Based on our on-site observations and review, the 2x10 is adequate as installed; no further action is required.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 984-344-4691.

Respectfully Submitted, Patrick Ruff



Reviewing Engineer: Kyle Edwards, PE, CWI