



END REACTION (UP TO) REQ'D STUDS FOR (2) PLY HEADER

1700 1

3400 2

5100 3

6800 4

8500 5

10200 6

11900 7

13600 8

15300 9