# **DESIGN PROFESSIONAL INSPECTION FORM**

RECORD OF THE INSPECTION OF A **COMPONENT OR ELEMENT** BY A NC LICENSED ARCHITECT OR ENGINEER

**Project Information:** 

| Residential Single-Family Project: Yes | Commercial Project: <b>No</b> |
|--|-------------------------------|
| Code Enforcement Project No:           | Permit No:2412-0070           |
| Project Name: Woodgrove 138            | Owner: DR Horton              |
| Project Address: 132 Paper Birch Way   | Suite No:                     |
| Date Inspected: 2-18-25                | Contractor Name:              |
| Component Inspected: Monoslab/Footings |                               |

Responsible Licensed NC Architect or NC Engineer

| Name:            | Bryant Mueller, PE        |         |  |
|------------------|---------------------------|---------|--|
| Firm Name:       | TM Engineering, Inc.      |         |  |
| Phone Numbers:   | Office: 919-468-2545      | Mobile: |  |
| Email Address:   | bryantm@tmengineering.org |         |  |
| Mailing Address: |                           |         |  |

**APPLICABLE CODE: NCRC** Sections R403.1.1, R403.1.4, R403.1.5

2018 NCBC = 2018 NC Building Code; 2018 NCRC = 2018 NC Residential Code

Describe Element/Component/Type of Inspection: \*

3rd party inspection of layout and dimensions per town approved onsite plans per applicable

2018 NCRC. See attached letter for site specific details and primary language regarding TME services. Porch included

### Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per subsection (b2) of NC G.S. 153A-352 and is in compliance with the approved plans & specifications for the project. This inspection is in compliance with all of the requirements of the above referenced

code. Attach any additional documents if needed.

Licensed Architect or Engineer Date

# SEAL SEAL OSO303 SEAL OSO303 SEAL OSO303

# Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of Article 160A-413.5., Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.

<sup>\*(</sup>subgrade form/letter may also be required)



## **Report of Foundation Bearing Conditions**

Project: Woodgrove 138 3rd Party

Location: Fuquay Client: DR Horton Date: February 18,2025



TM Engineering, Inc. has inspected foundation bearing conditions for the above referenced construction. Our evaluation consisted of visually evaluating the exposed subgrades and by probing with a 1/2 inch steel rod. Dynamic cone penetrometer techniques were used to correlate surface soil conditions to bearing capacity. Foundations were excavated up to 1.50 ft below site grade. Results indicate the exposed soils to have penetration resistance which will provide the specified minimum 2,000 PSF of bearing capacity. It should be noted that minor cracking commonly occurs in construction for various reasons including but not limited to, temperature fluctuations relative to expansion and contraction of materials, concrete shrinkage, changes in moisture content, improper construction, and normal settlement. No warranty is implied for such items by this letter. Additionally, exposure of the soil subgrades to inclimate weather may compromise conditions requiring repairs and reinspection.

### TME Notes included:

- Front porch included
- 3rd party inspection of layout and dimensions noted to be consistent with onsite plans
- Design Professional Inspection Form attached referencing 2018 NCRC sections R403.1.1, R403.1.4, & R403.1.5
- Vapor barrier and insulation present

Sincerely,

### TM Engineering, Inc.(C3201)



