



Structural  
Engineering  
Consultants

Mr. Jose Rubio  
143 Knight Road  
Broadway, NC 27505

June 30, 2025

Dear Mr. Rubio,

We observed the soil condition for the perimeter foundation and interior spread footings at the referenced location. We encountered soft silty soils throughout the entire site.

We instructed the contractor to remove the top 24" of soil at all footing locations and fill with 24" of #57 stone.

The site is now adequately prepared for pouring concrete.

Please let us know if you need further guidance or information.

Regards,



Henry D. Stewart, PE  
NC Professional Engineer License #23015  
HDS Engineering, Inc.  
Firm License #C-4889