# SITE/SC EVALUATION FOR ON-SI WASTEWATER

**APPLICANT NAME** _____ **DAT** _____

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| ***LANDSCAPE POSITION*** | .1940 | L | L | L | | | | | | | |
| ***SLOPE (%)*** | .1940 | 2 | 2 | 2 | | | | | | | |
| ***HORIZON 1 DEPTH*** | | 0-18 | | | | | | | | | |
| Texture Group | .1941(A)(1) | SL | | | | | | | | | |
| Consistence | .1941 | FR | | | | | | | | | |
| Structure | .1941(A)(2) | GR | | | | | | | | | |
| Mineralogy | .1941(A)(3) | NSNP | | | | | | | | | |
| ***HORIZON 2 DEPTH*** | | 18-36 | | | | | | | | | |
| Texture Group | .1941(A)(1) | SCL | | | | | | | | | |
| Consistence | .1941 | FR | | | | | | | | | |
| Structure | .1941(A)(2) | CR | | | | | | | | | |
| Mineralogy | .1941(A)(3) | SSSP | | | | | | | | | |
| ***HORIZON 3 DEPTH*** | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| ***HORIZON 4 DEPTH*** | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| ***SOIL WETNESS*** | .1942 | 36" | 36" | | | | | | | | |
| ***RESTRICTIVE HORIZON*** | .1944 | | | | | | | | | | |
| ***SAPROLITE*** | .1943/.1956 | | | | | | | | | | |
| ***CLASSIFICATION*** | .1948 | | | | | | | | | | |
| ***LONG TERM ACCEPTANCE RATE*** | .1955 | .4 | .4 | | | | | | | | |

year
on
C 0050
il 16, 1990

Municipality - / C. Williams
Not responsible for driveway




Note
Property shown hereon is located
in Watershed District IV, Protected.