Client:	QUEST DEV.	Date:	8/12/2025
Project:		Input by:	LENNY NORRIS
Address:		Job Name:	HENSLEY
		Project #:	

GDH 10' SL Kerto-S LVL 1.750" X 11.875" 3-Ply - PASSED

Level: Level



Member Information

Type:	Girder	Application:	Floor
Plies:	3	Design Method:	ASD
Moisture Condition:	Dry	Building Code:	IBC/IRC 2015
Deflection LL:	480	Load Sharing:	Yes
Deflection TL:	360	Deck:	Not Checked
Importance:	Normal - II		
Temperature:	Temp <= 100°F		

Reactions UNPATTERNED lb (Uplift)

Brg	Direction	Live	Dead	Snow	Wind	Const
1	Vertical	0	3421	3146	0	0
2	Vertical	0	2599	1726	0	0

Bearings

Bearing	Length	Dir.	Cap.	React D/L lb	Total	Ld. Case	Ld. Comb.
1 - SPF End Grain	6.000"	Vert	25%	3421 / 3146	6567	L	D+S
2 - SPF End Grain	6.000"	Vert	16%	2599 / 1726	4325	L	D+S

Analysis Results

Analysis	Actual	Location	Allowed	Capacity	Comb.	Case
Moment	16943 ft-lb	6'3 1/2"	35719 ft-lb	47%	D+S	L
Unbraced	16943 ft-lb	6'3 1/2"	16973 ft-lb	100%	D+S	L
Shear	4774 lb	1'5 7/8"	15295 lb	31%	D+S	L
LL Defl inch	0.107 (L/1162)	5'8 3/8"	0.259 (L/480)	41%	S	L
TL Defl inch	0.233 (L/534)	5'8 15/16"	0.346 (L/360)	67%	D+S	L

Design Notes

1 Provide support to prevent lateral movement and rotation at the end bearings.
2 Fasten all plies using 2 rows of 10d Box nails (.128x3") at 12" o.c. Maximum end distance not to exceed 6". Nail from both sides.
3 Refer to last page of calculations for fasteners required for specified loads.
4 Girders are designed to be supported on bottom edge only and across their full width.
5 Top loads must be supported equally by all plies.
6 Top must be laterally braced at a maximum of 7'10 3/8" o.c.
7 Bottom must be laterally braced at end bearings.
8 Lateral slenderness ratio based on single ply width.

ID	Load Type	Location	Trib Width	Side	Dead 0.9	Live 1	Snow 1.15	Wind 1.6	Const. 1.25	Comments
1	Point	0-2-12		Top	886 lb	0 lb	886 lb	0 lb	0 lb	D2 TRUSS
	Bearing Length	0-3-8								
2	Point	2-2-12		Top	886 lb	0 lb	886 lb	0 lb	0 lb	D2 TRUSS
	Bearing Length	0-3-8								
3	Point	4-2-12		Top	886 lb	0 lb	886 lb	0 lb	0 lb	D2 TRUSS

Continued on page 2...

Notes

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

Lumber

1. Dry service conditions, unless noted otherwise
2. LVL not to be treated with fire retardant or corrosive chemicals

Handling & Installation

1. LVL beams must not be cut or drilled
2. Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals
3. Damaged Beams must not be used
4. Design assumes top edge is laterally restrained
5. Provide lateral support at bearing points to avoid lateral displacement and rotation
6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 2/28/2028

Manufacturer Info

Metsä Wood
301 Merritt 7 Building, 2nd Floor
Norwalk, CT 06851
(800) 622-5850
www.metsawood.com/us

Client:	QUEST DEV.	Date:	8/12/2025
Project:		Input by:	LENNY NORRIS
Address:		Job Name:	HENSLEY
		Project #:	

GDH 10' SL Kerto-S LVL 1.750" X 11.875" 3-Ply - PASSED

Level: Level



...Continued from page 1

ID	Load Type	Location	Trib Width	Side	Dead 0.9	Live 1	Snow 1.15	Wind 1.6	Const. 1.25	Comments
	Bearing Length	0-3-8								
4	Part. Uniform	6-3-8 to 11-3-0	1-0-0	Top	200 PSF	0 PSF	0 PSF	0 PSF	0 PSF	GABLE END/WALL
5	Point	6-3-8		Top	2214 lb	0 lb	2214 lb	0 lb	0 lb	D3 TRUSS
	Bearing Length	0-3-8								
	Self Weight				14 PLF					

Notes

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

Lumber

1. Dry service conditions, unless noted otherwise
2. LVL not to be treated with fire retardant or corrosive chemicals

Handling & Installation

1. LVL beams must not be cut or drilled
2. Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals
3. Damaged Beams must not be used
4. Design assumes top edge is laterally restrained
5. Provide lateral support at bearing points to avoid lateral displacement and rotation
6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 2/28/2028

Manufacturer Info

Metsä Wood
301 Merritt 7 Building, 2nd Floor
Norwalk, CT 06851
(800) 622-5850
www.metsawood.com/us

Client:	QUEST DEV.	Date:	8/12/2025
Project:		Input by:	LENNY NORRIS
Address:		Job Name:	HENSLEY
		Project #:	

GDH 10' SL Kerto-S LVL 1.750" X 11.875" 3-Ply - PASSED

Level: Level

Multi-Ply Analysis

Fasten all plies using 2 rows of 10d Box nails (.128x3") at 12" o.c.. Nail from both sides. Maximum end distance not to exceed 6".

Capacity	0.0 %
Load	0.0 PLF
Yield Limit per Foot	163.7 PLF
Yield Limit per Fastener	81.9 lb.
C_M	1
Yield Mode	IV
Edge Distance	1 1/2"
Min. End Distance	3"
Load Combination	
Duration Factor	1.00

Notes

Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

Lumber

1. Dry service conditions, unless noted otherwise
2. LVL not to be treated with fire retardant or corrosive chemicals

Handling & Installation

1. LVL beams must not be cut or drilled
2. Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals
3. Damaged Beams must not be used
4. Design assumes top edge is laterally restrained
5. Provide lateral support at bearing points to avoid lateral displacement and rotation
6. For flat roofs provide proper drainage to prevent ponding

This design is valid until 2/28/2028

Manufacturer Info

Metsä Wood
301 Merritt 7 Building, 2nd Floor
Norwalk, CT 06851
(800) 622-5850
www.metsawood.com/us