Wayne R. Dashield, PE

421-B South Bright Leaf Blvd. Smithfield, NC 27577

(919) 934-0961

January 8, 2025

Re: Ample Storage
Permit # BCOM 2312-0298
Tower Truss Layout Inspection Building "A"
404 East Jackson Blvd
Erwin, North Carolina

Att. Harnett County Inspection

Dear Sir- Madam:

On January 07, 2025 I made an onsite visit to the proposed Ample Storage Facility located at 404 East Jackson Blvd in Erwin, NC. The purpose of this visit was to act as a third party inspector for the inspection of the installed wood trusses for 30' by 30' existing exterior walls with a 24" spacing of the trusses for the Tower 1.

I was able to access the truss area though an attic access opening furnished by the contractor. The truss layout consisted of the following

Truss Member	Number of Trusses
CJ1	18
CJ2	8
CJ3	8
CT1	1
HGT1	2
HJ1	4
SD1	2
SD2	2
SD3	2

All of the trusses were anchored to the existing exterior walls with hurricane anchors. I have inspected the contractors' installation of the necessary items. I will certify that the contractor has met requirements of the construction documents and the 2018 State of North Carolina Building Code.

If I can be of any more assistance, please feel free to contact me.

Yours truly, Wayne R. Dashield, PE

APPENDIX G DESIGN PROFESSIONAL INSPECTION FORM

RECORD OF THE INSPECTION OF A **COMPONENT OR ELEMENT** BY A NC LICENSED ARCHITECT OR ENGINEER

Project Information:

Residential Single-Family Project: Y N	Commercial Project: 10 N
Code Enforcement Project No:	Permit No: BCOM 2312-0298
Project Name: "BLD"A"	Owner: Ample STORACE
Project Address: 464 EAST JACKSON BLUP	Suite No:
Date Inspected: 01/07/25	Contractor Name: Ample 5768 ACE
Component Inspected: Roof TRUSSES	

Responsible Licensed NC Architect or NC Engineer

Name:	WAYNER. PASHIELD PE
Firm Name:	WAYNER DASHIELD PE
Phone Numbers:	Office: 9/9.934096/Mobile:
Email Address:	WRDASHIELD, PE @ GMAIL, Com
Mailing Address:	421-BS BRICHTLEAF BILD SMIFH FIELD NC

APPLICABLE CODE	A	P	P	L	C	A	В	LE	C	0	D	E
-----------------	---	---	---	---	---	---	---	----	---	---	---	---

2018 NC. BUILDING CEDE

2018 NCBC = 2018 NC Building Code: 2018 NCRC = 2018 NC Residential Code

Describe Element/Component/Type of Inspection: *

ROOT TRUSSES FOR TOWER 1

*[subgrade form/letter may also be required]

Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per G.S. 160D-11-6 and is in compliance with the Code or other proposal of the architect or engineer for the project. This inspection is in compliance with all of the requirements of the above referenced.

code. Attach any additional documents if needed.

Licensed Architect or Engineer

Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of G.S. 160D-11-1, Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.

Minister H.

STATE: Fax. 910-329-1664 Ph. 910-329-9631 Holly Ridge, NC 28445

501 N. Hwy 17


Erwin CILK: ADDRESS: **10BNAME:**

Ample Storage / TOWER 1 LO241117

NC

QUOTE:

30-00-08



30-00-00

SHOP DRAWING APPROVALS:
THIS LAYOUT IS THE SOLE SOURCE FOR FABRICATION OF TRUSSES AND VOIDS.
ALL REVIOUS ACCHIECTURAL OR OTHER TRUSS LAYOUTS. REVIEW AND
APPROVAL OF THIS LAYOUT MUST BE RECEIVED BLFOKE ANY TRUSSES ARE
FABRICATED. VERIFY ALL CONDITIONS TO INSURE AGAINST CHANGES THAT WILL
RESULT IN EXTRACTORAGES TO YOU. PIELD BRACING IS NOT THE RESPONSIBILITY OF THE TRUSS FABRICATOR, TRUSS DESIGNER, OR PLATE MANUFACTURER. PERSONS ERECTING TRUSSES ARE CAUGHDED TO SERK PROFESSIONAL ADVICE REGARDING TERRORIVARY AND REACTING MELCH MAY BE REQUIRED IN SECRETCA ADVICE REGARDING TERRORIVARY AND REACTING WHICH MAY BE REQUIRED IN SECRETCATIONS. TRUSSES SHATEL BY BEATHINGS DAWINGS FOR SHEATHINGSPURLIN SECRET BEATHINGS DAWINGS FOR SHEATHINGSPURLIN SECONDAL INJURY. REFER TO TRUSS BRAINED MAY AND BOTTOM CHORDS. TRUSSES MUST BE LANDLED WITH EXTREME CARE TO PREVENT DARAGE OR PERSONAL INJURY. REFER TO TRUSS BRAINED DRAWINGS FOR CONNECTION AND BRACING REQUIREMENTS. THESE CALCULATIONS ARE SUPPLIED IN ORDER FOR THE ENGINEER OF RECORD TO CONCERNING TRUSS PLACEMENT.



RECEIPT OF PAYMENT STATE FARM INSURANCE COMPANIES

PAYMENT DATE: 01-08-2025

SELMA, NC 27576-8403 8077 NC HIGHWAY 96 WAYNE R DASHIELD POLICYHOLDER(S)

\$216.70 **TNUOMA**

CHECK # 8237 CHECK / BEL #

9001 7540 EXECUTIVE PROTECTOR-DASHIELD, WAYNE POLICY DESCRIPTION/POLICY NUMBER

:GIA9 TNUOMA JĄTOT

\$216.70

EJAUTANDIS DEISIAOHTURE

KATELIN BRYANT

9797-167 (797) **MILSON, NC 27896** 2421-A AIRPORT BLVD LAKE, JANA L **AGENT**

SUBJECT TO COLLECTION AND POLICY PROVISIONS. WE APPRECIATE YOUR BUSINESS. THANK YOU FOR YOUR PAYMENT ON THE ABOVE POLICY(IES). PAYMENTS ARE RECEIVED