

August 17, 2018

Letitia Webb  
1583 Wire Road  
Bunnlevel, NC 28323

**RE: Existing Septic System Inspection BRES 1807-0052  
1583 Wire Road**

Dear Ms. Webb,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

\_\_\_\_\_ 1. Uncover outlet lid on septic tank and break seal

\_\_\_\_\_ 2. Have system pumped out

\_\_\_\_\_ 3. Replace sanitary T

**X 4. Other - Outlet end of septic tank was not uncovered, only the inlet lid, and the outlet lid shall be uncovered. Tank may require sewage pumping. The sewage level was higher than the inlet pipe. Call me when this is ready so that I can reinspect.**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S.  
Environmental Health Specialist  
Harnett County Department of Public Health  
Environmental Health

AC/sgs  
Copy - Central Permitting