

January 31, 2019

Deannie S Weaver
1097 Tarheel Rd
Benson, NC 27504

RE: Status of Permit Application- BRES1901-0015

Ms. Weaver,

An attempt was made to evaluate your property for the purpose of issuing a permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover Outlet lid on septic tank and break seal (\$25.00 fee incurred)
- 2. Have system pumped out
- 3. Replace Sanitary T
- 4. Other – Corner property irons shall be located, uncovered, and marked. Property lines shall be clearly marked (based off irons). Proposed Mod. Corner locations shall be flagged onsite. Accurate site plan shall be provided including Mod. Location and property line setbacks (Revision Required).

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S
Environmental Health Specialist
Harnett County Department of Public Health

AC/kh
Copy - Central Permitting