Wayne R. Dashield, PE

421-B South Bright Leaf Blvd. Smithfield, NC 27577

(919) 934-0961

Fax (919) 934-0967

July 01, 2019

Re: Foundation Inspection 7945 NC Hwy 42 Holly Springs, NC

Dear Sir-Madam


On June 28, 2019 I made an on site visit to the mobile Home Located at 7945 NC Hwy 42 in Holly Springs, NC for a Foundation inspection of the 26' by 65' mobile home. The purpose of this visit was to evaluate the mobile home foundation for HUD requirements for HUD Permanent Foundation of Manufactured Home. Chapter 5 of the Handbook for Permanent Foundation Guide for Manufactured Housing was used as a guide for this inspection.

Based on my inspection the foundation for the mobile home all of the requirements meet all the HUD Permanent Foundation Requirements except for the tie downs for up lift. The existing foundation wall does not have a provision for the uplift for the mobile home for the wind loads. I will recommend that THDHLS concrete anchors be install @ 14' O.C. along the exterior main I beams. (See attached sheet)

I will certify that by the completion of addition of the concrete that the mobile home will completely satisfy the requirements HUD Permanent Foundations. If I can be of any more assistance please feel free to contact me.

Yours truly,

Wayne R. Dashield, PE



WAYNE R. DASHIELD, PE

421—B BRIGHT LEAF BLVD. SMITHFIELD, NC 27577

919-934 -0961

