

April 9th, 2019

William Weiss  
147 Hawksworth Place  
Cameron, NC 28326

**RE: Existing Tank Application # BRES1903-0055**

Mr. Weiss,

An attempt was made to evaluate your property for the purpose of issuing an existing tank permit. The evaluation could not be completed for one or more of the following reasons.

\_\_\_ 1. Uncover Outlet lid on septic tank and break seal (\$25.00 fee incurred).

\_\_\_ 2. Have system pumped out

\_\_\_ 3. Replace Sanitary T

\_\_\_ 4. **Other – Unapproved Placement- Pool placed in permitted septic repair area. Electrical conduit and water line run through permitting existed septic area. Soil Scientist report required verifying adequate repair area with pool.**

Your application will be put on hold until the selected items above have been addressed.

When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin R.E.H.S  
Environmental Health Specialist

Harnett County Department of Public Health

AC/kh  
Copy - Central Permitting