

R O N A L D L . K N O T T , P . E .

801 CRICKET KNOLL ROAD
FUQUAY-VARINA, NC 27526
(919) 417-1962

Nov 25, 2019

Juan Carlos and Darlene Leon
76 Virginia Lane
Cameron, NC

RE: Engineering Review of Footing Offset and Size for 76 Virginia Lane, Cameron, NC


Darlene:

I reviewed the as-built condition of the new footings adjacent to the existing foundation curtain wall. The new piers are 16"x16" and the concrete footings extend beyond the piers in all directions.

The size and projection of these footings are adequate for code required loading conditions for this application.

It has been my pleasure to help in this effort. If you have any questions, please call. I'm glad to assist.

Sincerely,



Ronald L. Knott, P.E.
(919) 417-1962

