





See notes on roof



Min 2x8 @ 16" oc ceiling joists in lower 1/3 of rafter span required by code in addition to collar ties or provide engineering

Headers must be bolted to posts

Continue on Back ->