



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

3/10/2022

SUBJECT: BRES2110-0044
BUILDING RESIDENTIAL

To: TRAN DINH

Here are the results of all Inspections located at **82 OLD SALEM DR:**

Inspection Type: ADDRESS
Scheduled Date/Time:
Completed Date/Time:
Inspector: GIS Bucket
Result:
Remarks:
Notes:

Inspection Type: ENVIR OPERATIONS PERMIT
Scheduled Date/Time:
Completed Date/Time:
Inspector: EH Bucket
Result:
Remarks:
Notes:

Inspection Type: FOOTING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: MFH FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ZONING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Planning Bucket
Result:
Remarks:
Notes:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 12/21/2021
Completed Date/Time: 12/21/2021
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: Work not complete, ok to side ends, provide architect engineer pier design due to over 1/4 piers being above 36" finished grade



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 2/8/2022
Completed Date/Time: 2/8/2022
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: Unable to locate engineer letter addressing pier height

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 2/9/2022
Completed Date/Time: 2/9/2022
Inspector: Slade Burton Lawson III
Result: FAIL W/ PENALTY
Remarks:
Notes: No engineer letter addressing pier height