

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

10/5/2022

SUBJECT: BRES2203-0010 BUILDING RESIDENTIAL

To: Riggs Custom Construction

Here are the results of all Inspections located at 7150 NC 27 E:

Inspection Type: FINAL** Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type:	FOOTING
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type:	FOUNDATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type:	SLAB
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylo
Result:	
Remarks:	
Notes:	



50		Harnett County 420 Mckinney Pkwy		
Harnett county North Carolina	LILLING Phone: Fax:			
Inspection Type Scheduled Date Completed Dat Inspector: Result: Remarks: Notes:	e/Time:	INSULATION Deen Taylor		
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	ROUGH IN REINSPECT Deen Taylor		
Inspection Type Scheduled Date Completed Dat Inspector: Result: Remarks: Notes:	e/Time:	MONO SLAB Deen Taylor		
Inspection Type Scheduled Date Completed Dat Inspector: Result: Remarks: Notes:	e/Time:	MONO SLAB 3/30/2022 3/30/2022 Deen Taylor DISAPPROVED Cus req this be put on w/underslab trades No engineer plan for monolithic slab pour, only footing and stemwall		
Inspection Type Scheduled Date Completed Dat Inspector: Result: Remarks: Notes:	e/Time:	MONO SLAB 5/31/2022 5/31/2022 Deen Taylor DISAPPROVED Original sealed plans called for stemwall slab. Monolithic slab was never inspected nor approved and now requires engineers approval		



50		Harnett County 420 Mckinney Pkwy		
Harnett c o u n t y NORTH CAROLINA	LILLING Phone: Fax:	-		
Inspection Typ Scheduled Dat Completed Dat Inspector: Result: Remarks: Notes:	e/Time:			
Inspection Typ Scheduled Dat Completed Dat Inspector: Result: Remarks: Notes:	e/Time:			
Inspection Type: Scheduled Date/Time: Completed Date/Time Inspector: Result: Remarks: Notes:	6/10/2022 Deen Taylor DISAPPROVED			
		see eng letter		
		see eng letter		
		The sealed engineer letter must state that the monolithic slab that has been poured meets or exceeds the requirements of the slab originally designed by the engineer for the approved set of plans.		

