



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

5/25/2023

SUBJECT: BRES2301-0005
BUILDING RESIDENTIAL

To: Ricky Smith

Here are the results of all Inspections located at **149 SMITH DR:**

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: INSULATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: MONO SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: OPEN FLOOR
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: UNDER SLAB TRADES
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN REINSPECT
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 3/15/2023
Completed Date/Time: 3/15/2023
Inspector: Deen Taylor
Result: APPROVED
Remarks:
Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time: 3/23/2023
Completed Date/Time: 3/23/2023
Inspector: Deen Taylor
Result: APPROVED
Remarks:
Notes:



Harnett County
420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: ROUGH IN

Scheduled Date/Time: 5/24/2023

Completed Date/Time: 5/24/2023

Inspector: Scott Guy

Result: DISAPPROVED

Remarks:

Notes:

-fire caulking not completed-insulation vents not installed -plumbing rough in not complete.-
framing around and fire stop plumbing drain lines in center first floor area -Smoke detector
circuit must be tied in with existing circuit. Do not insulate