

Spout Springs Emergency Services

Station: **ST1**
Shifts Or Platoon: **C Shift**

Location: 445 Arlington DR Cameron NC 28326 Prestige Dr/Crutchfield Dr	Incident Type: 111 - Building fire
Lat/Long: N 35° 15' 53.35" W 79° 2' 2.75"	FDID: 04312 Incident #: 2022-88257 Exposure ID: 67677633 Exposure #: 0 Incident Date: 07/31/2022 Dispatch Run #: 2207-088257
Location Type: 1 - Street address Cross Street, Directions or National Grid: Prestige Dr/Crutchfield Dr	

Report Completed by:	Mullen , Jason W	ID: 3884jm01	Date: 07/31/2022
Report Reviewed by:	Burris , Rodney A	ID: 1656rb01	Date: 08/01/2022
Report Printed by:	Hardy, Angi	ID: 5747ah01	Date: 8/1/2022 Time: 11:47

Structure Type: Enclosed building	Property Use: 419 - 1 or 2 family dwelling
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input checked="" type="checkbox"/> Cause of Ignition: Failure of equipment or heat source
Aid Given or Received: Automatic aid received	Primary action taken: 11 - Extinguishment by fire service personnel
Additional actions: 58 - Operate apparatus or vehicle , 81 - Incident command	
Losses	Pre-Incident Values
Property: \$0.00	Property: \$202,540.00
Contents: \$4,200.00	Contents: \$35,000.00
Total: \$4,200.00	Total: \$237,540.00
Civilian Injuries: 0	Fire Service Injuries: 0
Civilian Fatalities: 0	Fire Service Fatalities: 0
Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 3	Total # of personnel on call: 4

Special Studies	
COVID 19 was a factor in this incident.	Unknown.

Neighboring Agencies
Agency Name: Anderson Creek Agency ID: 04301 Agency Type: Fire
Agency Name: Benhaven Agency ID: 04316 Agency Type: Fire
Agency Name: Crains Creek Volunteer Fire Department Agency ID: 06323 Agency Type: Fire
Agency Name: Flat Branch Agency ID: 04308 Agency Type: Fire
Agency Name: Fort Bragg Fire Agency ID: 02608 Agency Type: Fire
Agency Name: Spring Lake Fire Department Agency ID: 02616 Agency Type: Fire

Narrative from dispatch:
07/31/2022 01:49:53MW2102 [1] Multi-Jurisdiction Harnett County EMS Incident #: 2207-088258

07/31/2022 01:50:17MW2102 [2] [ProQA: Case Entry Complete] Problem Description: REPORTED BUILDING/STRUCTURE FIRE Chief Complaint: 69, CCText: Structure Fire [Shared]

07/31/2022 01:50:22AB1673 [3] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Spout Springs Fire. Case Number(s): 07312022-0000852. requested by F1. [Shared]

07/31/2022 01:50:22AB1673 [4] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Benhaven Fire. Case Number(s): BHFD2200580. requested by F13. [Shared]

07/31/2022 01:50:22AB1673 [5] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Anderson Creek Fire. Case Number(s): ACFD2200411. requested by F3. [Shared]

07/31/2022 01:50:23AB1673 [6] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Fort Bragg Fire. Case Number(s): 07312022-0000065. requested by FFBS6. [Shared]

07/31/2022 01:50:23AB1673 [7] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Crains Creek Fire. Case Number(s): 07312022-0000057. requested by FCC23. [Shared]

07/31/2022 01:50:23AB1673 [8] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Spring Lake Fire. Case Number(s): 07312022-0000042. requested by SL2251. [Shared]

07/31/2022 01:50:23AB1673 [9] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Flat Branch Fire. Case Number(s): 07312022-0000219. requested by F2. [Shared]

07/31/2022 01:50:26MW2102 [10] [ProQA Dispatch] Dispatch Level: 69E06 (Residential (single)) Response Text: Code 3 [Shared]

07/31/2022 01:50:26MW2102 [11] [ProQA: Key Questions] > Residential (single). [Shared]

07/31/2022 01:50:28AB1673 [12] Automatic Case Number(s) issued for Incident #[2207-088258], Jurisdiction: Anderson Creek EMS. Case Number(s): ACEMS2201724. requested by MED3. [Shared]

07/31/2022 01:51:24MW2102 [13] [ProQA: Key Questions] > Caller not inside bldg. > Multi-story: 2 > No one trapped. > Fire loc: SPARE ROOM > Floor: 1ST FLOOR > No inj. [Shared]

07/31/2022 01:52:08KW2241 [14] FT BRAGG ADV [Shared]

07/31/2022 01:52:23AB1673 [15] MED3 DIRECT [Shared]

07/31/2022 01:53:14MW2102 [16] Duplicate call appended to incident at 01:53:14 [Shared]

07/31/2022 01:54:06KW2241 [17] MOORE CO ADV [Shared]

07/31/2022 01:54:11AB1673 [18] FFBS6 ENG 6 ENR [Shared]

07/31/2022 01:54:15MW2102 [19] CEMC ADV [Shared]

07/31/2022 01:56:46AB1673 [20] FCC23 ENG 236 ENR [Shared]

07/31/2022 01:58:37AB1673 [21] F143 105 IC LIGHT SM SHOWING OUT INV [Shared]

07/31/2022 01:59:04AB1673 [22] SL2251 CUA ENG 1111 ENR [Shared]

07/31/2022 01:59:20AB1673 [23] F143 ALL OCC OUT OF THE RESD//HEAVY SMOKE SHOWING [Shared]

07/31/2022 02:02:11DF2291 [24] 103 ASSUMING IC [Shared]

07/31/2022 02:03:15DF2291 [25] FIRE OUT AT THIS TIME [Shared]

07/31/2022 02:05:54DF2291 [26] 103 XCEL UNITS NOT ONSC [Shared]

07/31/2022 02:07:11DF2291 [27] [Harnett County EMS] has closed their incident [2207-088258]

07/31/2022 02:20:13DF2291 [28] Automatic Case Number(s) issued for Incident #[2207-088257], Jurisdiction: Fire Marshal. Case Number(s): 07312022-0000139. requested by FM. [Shared]

07/31/2022 02:21:47DF2291 [29] FM4 DIRECT [Shared]

NARRATIVE (2)

Narrative Title: 22-88257

Narrative Author: Mullen, Jason

Narrative Date: 07/31/2022 04:55:01

Narrative Apparatus ID: 143

Narrative:

Dispatched to 445 Arlington Drive reference RSF. 143, 144, and 183 responded. Automatic Aid from BES, ACES, FBE6, SLFD, FBFD, and MC23 responded. 143 arrived and 105 established command while reporting a 2-story structure with light smoke showing, out investigating. Once scene lighting was set up, 105 upgraded the on-scene report to heavy smoke showing from division 1 and all occupants reported out of the structure. a 200-foot 1.75-inch attack line was pulled and entry was made through Division 1 Side A by 143 and FBE6 crews. FBE6 began a primary search while 143 and 1 FBE6 member made an attack. 183 and 144 arrived. 103 assumed command. The fire was quickly brought under control and extinguished with approximately 20 gallons of water. A primary search was completed with nothing found. All units not on scene were canceled. Crews then ventilated the structure with PPV fans. FM was requested and FM4 and FM2 responded. All aid units were released. Crews assisted FM with the initial investigation until released, assignment complete. Nothing further.