

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

## 4/21/2025

## SUBJECT: BRES2304-0017 BUILDING RESIDENTIAL

To: WEAVER HOMES INC.

Here are the results of all Inspections located at 141 SERINA WOODS DR:

Inspection Type:	FOOTING
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	James T Hall
Result:	
Remarks:	
Notes:	

ames T Hall

Inspection Type:	SLAB
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	James T Hall
Result:	
Remarks:	
Notes:	

Inspection Type:	FINAL**
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	James T Hall
Result:	
Remarks:	
Notes:	future house / not upfitted at this time





Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time:	ROUGH IN REINSPECT
Completed Date/Time:	
Inspector:	James T Hall
Result:	
Remarks:	eTRAKiT Inspection Request
Notes:	

Inspection Type:	ADDRESS
Scheduled Date/Time:	5/8/2023
Completed Date/Time:	5/12/2023
Inspector:	GIS Bucket
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	5/4/2023 5:15 PM WEAVER HOMES INC.

Contact Name: WEAVER HOMES INC. Site Address: 139 SERINA WOODS DR Phone: 9106302100 e-Mail: susan@weaver-homes.com

141 Serina Woods Dr

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	
Inspection Type:	

Inspection Type:	ENVIR OPERATIONS PERMIT
Scheduled Date/Time:	6/27/2023
Completed Date/Time:	6/27/2023
Inspector:	Mark Osborne
Result:	APPROVED
Remarks:	
Notes:	



Harnett NORTH CAROLINA

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	ROUGH IN
Scheduled Date/Time:	7/26/2023
Completed Date/Time:	7/26/2023
Inspector:	James T Hall
Result:	DISAPPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	5/4/2023 5:10 PM WEAVER HOMES INC.
	Gate Code : 0685
	Contact Name: WEAVER HOMES INC.
	Site Address: 139 SERINA WOODS DR
	Phone: 9106302100
	e-Mail: susan@weaver-homes.com

Fasten toilet flanges per codeFire caulk plumbing at top platePlumbing not vented through the roofSupport vent pipe in ceiling every 4' per codeFire caulk 3" pipe and water line at top plate and missing nail guards at door at bottom stairsStrap each side of garage doors from top plate to 1' below headerMissing anchor bolts at opening need 2 anchors per memberNeed stud under top plate joint first window on back wall upstairsMissing nails in hurricane straps on front wall upstairs

Inspection Type:	SEWER CONNECTION
Scheduled Date/Time:	7/27/2023
Completed Date/Time:	7/27/2023
Inspector:	James T Hall
Result:	APPROVED
Remarks:	
Notes:	

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result:	• •

Remarks: Notes: