

## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

11/6/2023

SUBJECT: **BRES2304-0054** 

**BUILDING RESIDENTIAL** 

To: ARMLAND LLC

Here are the results of all Inspections located at 2789 MCLEAN CHAPEL CHURCH RD:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FOOTING

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:





## **Harnett County**

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FINAL\*\*

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ROUGH IN Scheduled Date/Time: 6/2/2023 Completed Date/Time: 6/2/2023 Inspector: James T Hall Result: CANCELLED

Remarks:

No code for lock box



## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 6/6/2023
Completed Date/Time: 6/6/2023
Inspector: James T Hall
Result: DISAPPROVED
Remarks: code 2413
Notes: code 2413

1. Fire caulk plumbing at bottom plate at washer box 2. Need plumbing drain line test and water line test on for inspection 3. Need paperwork for lvl beam in kitchen 4. Duct work in front left bedroom needs to be in a chase and fire caulk chase 5. Seal all holes in floor at water

heater6. Need to see duct work and wiring for bathroom exhaust fans7. Replace cut floor joist at

crawl space door and remove old electrical boxes

Inspection Type: ROUGH IN REINSPECT

code 2413

Scheduled Date/Time: 7/24/2023 Completed Date/Time: 7/24/2023 Inspector: John B Kokoszka Result: APPROVED

Remarks: Notes:

Inspection Type: INSULATION
Scheduled Date/Time: 8/23/2023
Completed Date/Time: 8/23/2023
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes: lock box is 2413

Need to make sure you insulation at all location that you cut open. The insulation can't have gaps . Need to foam insulation around windows and doors that have been opened around

Inspection Type: INSULATION REINSPECTION

Scheduled Date/Time: 8/29/2023 Completed Date/Time: 8/29/2023 Inspector: James T Hall Result: APPROVED

Remarks: Notes:



## **Harnett County**

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: FINAL\*\*
Scheduled Date/Time: 11/3/2023
Completed Date/Time: 11/3/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes:

lock box code 2413

Inspector SPG changed the inspection assignment from SPG to JTH

1. Missing house numbers2. Missing front steps for porch and they need to be per code3.

Uncover ground rods for inspection