



**Harnett County**  
420 McKinney Pkwy  
LILLINGTON, NC 27546  
Phone:  
Fax:

7/28/2025

SUBJECT: **BRES2403-0042**  
**BUILDING RESIDENTIAL**

To: DRAY ALAN

Here are the results of all Inspections located at **5732 MCDUGALD RD:**

Inspection Type: FOOTING  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Steven Gazlay  
Result:  
Remarks:  
Notes:

Inspection Type: FOUNDATION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Steven Gazlay  
Result:  
Remarks:  
Notes:

Inspection Type: MONO SLAB  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Steven Gazlay  
Result:  
Remarks:  
Notes:

Inspection Type: SLAB  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Steven Gazlay  
Result:  
Remarks:  
Notes:



**Harnett County**  
420 McKinney Pkwy  
LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: FINAL\*\*  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Steven Gazlay  
Result:  
Remarks:  
Notes:

Inspection Type: ENVIR OPERATIONS PERMIT  
Scheduled Date/Time: 6/25/2024  
Completed Date/Time: 6/25/2024  
Inspector: Mark Osborne  
Result: APPROVED  
Remarks:  
Notes:

Inspection Type: ROUGH IN  
Scheduled Date/Time: 2/19/2025  
Completed Date/Time: 2/19/2025  
Inspector: Daniel L Floyd  
Result: DISAPPROVED  
Remarks:  
Notes: Per customer request and she wasn't sure if this was the correct inspection, but requested it anyways  
Not ready need to fire stop all penetrations for electrical in the top and bottom plates secure all wires and have them in the boxesNot plumbing tests on

Inspection Type: ROUGH IN REINSPECT  
Scheduled Date/Time: 2/25/2025  
Completed Date/Time: 2/25/2025  
Inspector: Daniel L Floyd  
Result: APPROVED  
Remarks:  
Notes:



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: INSULATION

Scheduled Date/Time: 4/2/2025

Completed Date/Time: 4/2/2025

Inspector: John B Kokoszka

Result: APPROVED

Remarks:

Notes: So a few areas around the windows and doors on the walls that day opened up, they are good Floor system or 30 they're good Foam insulation back rear ceiling need foam report at final Seen some of the ceiling, but the rest had plywood all over it from pre-existing Exterior walls that was not touched didn't look at pre-existing

Inspection Type: FINAL\*\*

Scheduled Date/Time: 7/28/2025

Completed Date/Time: 7/28/2025

Inspector: John B Kokoszka

Result: DISAPPROVED

Remarks:

Notes: Coming out the left side exit missing insulation and the board covering the electrical in the right cubbyhole I left open Need ladder for attic access missing weatherstripping and insulation at attic access Need to seal cut off pipe in closet at water heater LFront left steps landing needs to be the width of the steps 3 foot out no more 8 1/4 high from the top to the dirt from the bottom step Water heater drip pan needs to terminate to the outside