

**THOMPSON AND ASSOCIATES**

1149 Executive Circle  
Suite D-2  
Cary, North Carolina 27511  
(919) 465-1566

December 8, 2023

To: Mr. Brian Davis

Re: Bryant Residence  
1048 Jackson Road  
Fuquay-Varina, North Carolina 27526


Dear Mr. Davis:

As per your request, a field inspection was conducted at 1048 Jackson Road in Fuquay-Varina, North Carolina on December 8, 2023. The purpose of this field inspection was to investigate the pad construction located on the property associated with the construction of a proposed metal out building.

Upon initial inspection, the earthen area of the building pad was excavated. The organic material of the pad area had been stripped from the pad area and placed to the rear, outside of the pad area. The pad area was constructed out of earthen fill material borrowed on site adjacent to the pad area. The fill material, via visual inspection was found to be adequate. The area of the constructed building pad was probed with a 1/2" steel rod. All areas of the constructed building pad were found to be adequate. Based upon this inspection, it has been determined that the building pad area is adequately compacted and is ready to have the concrete slab poured.

I trust that this information will assist you in the completion of your project. If I can be of any further assistance please feel free to contact me.

Sincerely,

  
Randall L. Miller, PE  
Thompson and Associates, PA  
Lisc# C-0343

