

**\*Preliminary Soils Evaluation**

\*Not a Survey (sketched from a preliminary plat).

\*Septic system setbacks listed below for new lots.

- 1) 10' from property lines.
- 2) 100' from wells for primary and repair systems.
- 3) 50' from surface waters (streams, ponds, lakes).

\*Any mechanical disturbances such as grading, cutting and filling of the suitable soil areas can render areas unsuitable for future septic areas.



\*See accompanying report for additional information.

\*Base map sketched from preliminary plat map

\*Due to Soil Variability, Adams Soil Consulting cannot guarantee that the areas shown as suitable will be permitted by the local Health Department.

\*A more detailed soil evaluation should be performed prior to further subdivision.

**Preliminary Soils Evaluation  
Matthew Allen  
Lots 1-5 - Spring Hill Church Road  
Harnett County, NC**




**Legend**

Areas contain soils with 30 inches or more of useable material and have potential for conventional, modified conventional, LPP or ultra-shallow conventional septic systems. There may be inclusion of soils 24-29 inches to a restrictive horizon that will have potential for LPP septic systems.

**NE** Areas Not Evaluated

**US** Unsuitable Areas



**Adams**  
Soil Consulting  
919-414-6761  
Project #1165

\*Not a Survey  
(sketched from a preliminary plat)