

# **Flat Branch VFD**

Station: **DT2**Shifts Or Platoon: **Paid** 

Location:	
3375 Tho	mpson RD
Runnlevel	NC 28323

Bunnlevel NC 28323 Dewey Ln/Sandhills Ct

Lat/Long:

N 35° 18′ 18.14″ W 78° 50′ 6.08″

Zone:

FBFD - Flat Branch

Location Type: 1 - Street address Cross Street, Directions or National Grid:

Dewey Ln/Sandhills Ct

Incident Type: 111 - Building fire

FDID: 04308

Incident #: **2023-135365** Exposure ID: **76470360** 

Exposure #: 0

Incident Date: 10/30/2023 Dispatch Run #: 2310-135365

Report Completed by:	Winpegler , Kurt R	ID: 7689kw02	Date: 11/01/2023	
Report Reviewed by:	Winpegler , Kurt R	ID: 7689kw02	Date: 11/01/2023	
Report Printed by:	Brown, Joseph M	ID: 5279jb02	Date: 8/23/2024 Time: 10:09	

Structure T	ype: Enclosed bu	ilding	Property	Use: <b>419</b>	- 1	or 2 fan	nily dwell	ing		
Automatic	Extinguishment Sys	stem Pres	sent: 🗆	Detectors	e Pre	esent: 🗆	Cause of 1	ignitic	on: Unintentional	
Aid Given o	or Received: Auto	matic ai	d receiv	red Prima	ary a	ction take	en: <b>11 - E</b>	xting	juishment by fire service per	rsonnel
Additional a	actions:	12 - Sal	vage &	overhaul	, 1	4 - Conta	ain fire (w	ildla	nd)	
Losses		Pre-Inc	cident V	/alues						
Property:	\$30,000.00	Property	y: \$30	0,000.00		Civilian I	injuries:	0	Fire Service Injuries:	0
Contents:	\$0.00	Content	ts: <b>\$0.</b>	.00		Civilian F	atalities:	0	Fire Service Fatalities:	0
Total:	\$30,000.00	Total:	\$30	0,000.00		Total Cas	sualties:	0	Total Fire Service Casualties:	0
Total # of	apparatus on call:				6	Total #	of personn	el on	call:	16
Neighbor	ing Agencies									
Agency N	ame: Anderson Cr	eek Emer	raency S	ervices - F	DID	04301				

Total # of apparatus off call.		Total # of personner on call.	10
Neighboring Agencies			
Agency Name: Anderson Creek Emergency Se	ervices - FD1D	04301	
Agency ID: 04301			
Agency Type: Fire			
Agency Name: Lillington - FDID 04311			
Agency ID: 04311			
Agency Type: Fire			
Agency Name: Spring Lake - 02616			
Agency ID: 02616			
Agency Type: Fire			
Agency Name: Summerville - FDID 04313			
Agency ID: 04313			
Agency Type: Fire			
Agency Name: West Area - FDID 02622			
Agency ID: 02622			
Agency Type: Fire			

### Narrative from dispatch:

10/30/2023 15:11:07ABRYANT [1] [ProQA: Case Entry Complete] Problem Description: YARD ON FIRE, UNK WHERE ITS COMING FROM Chief Complaint: 67, CCText: Outside Fire

10/30/2023 15:11:16SALENT [2] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: Flat Branch Fire. Case Number(s): 10302023-0000277. requested by F2.

10/30/2023 15:12:19ABRYANT [3] [ProQA Dispatch] Dispatch Level: 82D02 (LARGE WILDLAND fire, structures THREATENED) Response Text: Code 3 Chief Complaint: 82, CCText: Vegetation / Wildland / Brush / Grass Fire

10/30/2023 15:12:19ABRYANT [4] [ProQA: Key Questions] > At loc (1st pty). > WILDLAND fire. > LARGE area. > Fire rptd by caller as not extinguished. > Threatening residential areas.

10/30/2023 15:12:47ABRYANT [5] [ProQA: Key Questions] > No one trapped or in immed danger. > Fire spreading. > Direction fire spreading: CLOSER TO CALLERS RESD > No inj. > Caller states no hazmat pres.

10/30/2023 15:13:39SALENT [6] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: HC Forestry Service, Case Number(s): 10302023-0000142. requested by FOR.

10/30/2023 15:15:01ABRYANT [7] Duplicate call appended to incident at 15:15:01

10/30/2023 15:18:30SALENT [8] F241 WORKING WOODS FIRE AND JUMPED THOMPSON RD MOVING TOWARDS BUNNLEVEL DISTRICT

10/30/2023 15:18:38SALENT [9] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: Summerville Bunnlevel Fire. Case Number(s): 10302023-0000402. requested by F11.

10/30/2023 15:18:47SALENT [10] F241 REQ BRUSH TRUCK

10/30/2023 15:20:31SALENT [11] F241 HAVE A STR ENDANGER UPGRADE STR FIRE

10/30/2023 15:20:48SALENT [12] Multi-Agency Harnett County EMS Incident #: 2310-135373

10/30/2023 15:20:48SALENT [13] [Page] Problem changed from Outside Fire to Residential Structure Fire by Harnett County Fire [Shared]

10/30/2023 15:21:04SALENT [14] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: Lillington

Fire. Case Number(s): 10302023-0000685. requested by F7. [Shared] 10/30/2023 15:21:05SALENT [15] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: Anderson Creek Fire, Case Number(s): ACFD2300566, requested by F3. [Shared] 10/30/2023 15:21:05SALENT [16] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: Spring Lake Fire, Case Number(s): 10302023-0000049, requested by FSL22, [Shared] 10/30/2023 15:21:05SALENT [17] Automatic Case Number(s) issued for Incident #[2310-135365], Jurisdiction: West Area Fire. Case Number(s): WAFD2300089. requested by FWA15. [Shared] 10/30/2023 15:21:27SALENT [18] Automatic Case Number(s) issued for Incident #[2310-135373], Jurisdiction: Anderson Creek EMS. Case Number(s): ACEMS2302577, requested by MED2, [Shared] 10/30/2023 15:21:30SALENT [19] [Page] Problem changed from Residential Structure Fire to Outside Fire by Harnett County Fire [Shared] 10/30/2023 15:21:32SLEE [20] Duplicate call appended to incident at 15:21:32 [Shared] 10/30/2023 15:22:41SALENT [21] 2 RESD STR ENDANGERED [Shared] 10/30/2023 15:22:57SALENT [22] MED2 WILL BE ENR SHORTLY [Shared] 10/30/2023 15:23:45SALENT [23] F7 DIRECT ON CALL [Shared] 10/30/2023 15:24:25SALENT [24] CUMBERLAND 2032 ENR [Shared] 10/30/2023 15:27:51SALENT [25] ONE SINGLE WIDE INVOLVED [Shared] 10/30/2023 15:29:26SLEE [26] SOUTH RIVER ADV [Shared] 10/30/2023 15:29:52SALENT [27] 203 REQ ADDITIONAL PAGE FOR STR FIRE MORE MAN POWER [Shared]

10/30/2023 15:29:56SALENT [28] [Page] Problem changed from Outside Fire to Residential Structure Fire by Harnett County

Fire [Shared]

10/30/2023 15:38:26SALENT [29] CUMBERLAND 1111 ENR [Shared] 10/30/2023 15:40:49SALENT [30] CUMBERLAND 1111 ON LOCATION [Shared] 10/30/2023 15:46:50SALENT [31] THOMPSON COMMD ADV ALL PERSONEL ACCOUNTED FOR [Shared] 10/30/2023 15:48:22SALENT [32] THOMPSON COMMD ADV FIRE ON THE EAST SIDE OF THOMPSON RD IS CONTAINED [Shared] 10/30/2023 16:14:10SALENT [33] THOMPSON RD COMD PAR COMPLETE ALL PERSONEL ACCOUNTED FOR AND SINGLE WIDE STR UNDER CONTROL [Shared] 10/30/2023 16:33:05SALENT [34] THOMPSON COMMD FIRE OUT SINGLE WIDE [Shared] 10/30/2023 17:24:37SALENT [35] CUMBERLAND CO 2032 AND 1111 RELEASED BY COMMND [Shared] 10/30/2023 17:36:36SALENT [36] [Harnett County EMS] has closed their incident [2310-135373]

# NARRATIVE (2)

**Narrative Title: NFIRS** 

Narrative Author: Hanway, Ashton Narrative Date: 11/01/2023 08:21:25

Narrative Apparatus ID: E241

#### Narrative:

## Command/ Initial Observations:

District 2 was dispatched to 3375 Thompson Road for an outside fire. Upon arrival E241 found a large woods fire with structures endangered, 241 established Thompson Road command. Upon initial investigation there were structures found to be endangered and prompted an upgrade to a structural fire response and due to the amount of woodland area on fire a brush truck was requested along with forestry.

#### Actions Taken:

See additional narratives for Wildland Fire and Structure Fire reporting purposes.

## Accountability:

Accountability officer maintained visual and verbal contact with all personnel throughout the duration of the incident and conducted personnel accountability checks throughout the incident. A total of 34 personnel were on scene, and all accounted for at each interval.

# Command Termination:

The scene was released to forestry and all mutual aid was released. 241 Terminated Thompson Road Command and all units returned to service.

# NARRATIVE (3)

Narrative Title: Wildland

Narrative Author: Hanway, Ashton
Narrative Date: 11/01/2023 07:51:21

Narrative Apparatus ID: E241

#### Narrative:

### Initial actions:

Upon arrival of 241 there was approximately 3 acres of mixed wooded and open area on fire. Fire personnel found 3 debris piles from possible land clearing to be heavily involved with fire and rapid fire growth was a result of high wind conditions at the time of the fire. The fire had also jumped the roadway to the East of Thompson Road and was spreading rapidly towards an occupied dwelling.

## Fire suppression:

Fire personnel from 241 initially began with creating a perimeter between adjacent structures for structural protection while extinguishing the head of the fire that was moving towards same. Fire personnel from District 11 utilized their Brush unit to contain the fire on the East side of Thompson Road and provide structural protection until Forestry units could arrive on scene. Fire personnel from 231 assisted with containment on the west side of Thompson Road and when the single wide structure became involved began primary fire attack on the structure (See Structural Fire Narrative for Details). Upon arrival of forestry a determination was made to have a plow line placed around the entirety of the West side and East side of Thompson Road for overall containment of the fire. Under direction of forestry fire personnel from 282 cut 3 trees that were aerial hazards to fire personnel and could further complicate suppression efforts. Fire personnel from district 11 placed an engine on the North Side of the Fire line that was created and utilized fire personnel from 281 & 282 to use copious amounts of water in an attempt to suppress the large debris plies. Ultimately 25 Gallons of foam had to be used to provide a blanket to prevent further heat and fire growth. Forestry Placed a plow line around the entire fire area and the fire was under control.

#### Water Supply:

2032,742, Cumberland 1111, and 243 were used for a water shuttle operation that was set up at a hydrant to the South on Thompson Road and a hydrant to the North at Thompson and Mclean Chapel Church Road. Approximately 10,000 gallons of water was utilized to contain/extinguish the fire.

Agencies involved in extinguishment:

District 11

District 7

District 2

District 3

Cumberland 1111

Cumberland 2034

# NARRATIVE (4)

Narrative Title: Structrure

Narrative Author: Hanway, Ashton Narrative Date: 11/01/2023 08:20:24

Narrative Apparatus ID: E241

Narrative:

Initial Observations:

Fire personnel had to transition to an offensive mode of operation of a single wide trailer that became involved as a result of the woods/wildland fire. The address of the singlewide trailer that became involved was 3370 Thompson Road. A Double wide that was on an adjacent property was also damaged as a result of the fire but only sustained exterior damage to the to the vinyl siding. The double wide did not have a physical address as it was placed recently for a possible new development.

## Fire suppression:

Fire personnel transitioned to an offensive attack on the structure and made entry to extinguish the fire. The trailer sustained over 50% damage to its entirety. The building was unsecure and did not require forcible entry to gain access. Fire personnel were able to contain the fire to the "D" delta side of the structure and it was found to have a double roof and insulation that would not allow for total extinguishment by hose line. Fire personnel utilized a chainsaw to cut the floor and flood areas of concern. Fire personnel also utilized a piercing nozzle to breach the roof area and flood concerned areas to ensure total extinguishment of the fire. Approximately 2500 gallons of water was used to fully extinguish the fire. Thermal imaging cameras were used to verify no hot spots or extension was found throughout the structure. The fire was extinguished, and no civilian or fire personnel injury occurred as a result of fire extinguishment.

### Water Supply:

2032,742, Cumberland1111, and 243 was used for a water shuttle operation that was set up at a hydrant to the South on Thompson Road and a hydrant to the North at Thompson and Mclean Chapel Church Road. Approximately 10,000 gallons of water was utilized to contain/extinguish the fire.

Agencies involved in extinguishment:

District 11 - 4 Personnel

District 7 - 3 Personnel

District 2 - 16 Personnel

District 3 - 3 Personnel

Cumberland 1111 - 2 Personnel

Cumberland 2034 - 6 Personnel

# NARRATIVE (5)

Narrative Title: Foam

Narrative Author: Winpegler, Kurt Narrative Date: 11/01/2023 10:12:59

Narrative Apparatus ID: n/a

Narrative:

25 gallons of National Foam (AR-AFFF) was used at 6%.

Personnel directly involved were.

Bain, Matthew Winpegler, Kurt Hanway, Ashton

Glass, Joshua (Anderson Creek)

Fire Controlled Date / Time:		10/30/2023 4:14:09 PM			
Unit	E241	Unit	T231		
Туре:	Tanker & pumper combination	Туре:	Tanker & pumper combination		
Use:	Suppression	Use:	Suppression		
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens		
# of People	3	# of People	3		
Alarm	10 /30/2023 15:10:15	Alarm	10 /30/2023 15:10:15		
Dispatched	10 /30/2023 15:11:15	Dispatched	10 /30/2023 15:11:15		
Enroute	10 /30/2023 15:12:09	Enroute	10 /30/2023 15:13:28		
Arrived	10 /30/2023 15:17:34	Arrived	10 /30/2023 15:20:04		
Cancelled	- //::	Cancelled	- / / : :		
Cleared Scene	10 /30/2023 18:00:38	<b>Cleared Scene</b>	10 /30/2023 18:00:39		
In Quarters	- / - / : :	In Quarters	- / / : :		
In Service	10 /30/2023 18:00:38	In Service	10 /30/2023 18:00:39		
Unit	E243	Unit	S281		
Type:	Tanker & pumper combination	Type:	Rescue unit		
Use:	Suppression	Use:	Suppression		
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens		
# of People	4	# of People	1		
Alarm	10 /30/2023 15:10:15	Alarm	10 /30/2023 15:10:15		
Dispatched	10 /30/2023 15:11:15	Dispatched	10 /30/2023 15:11:15		
Enroute	10 /30/2023 15:20:36	Enroute	10 /30/2023 15:24:32		
Arrived	10 /30/2023 15:25:04	Arrived	10 /30/2023 15:29:07		
Cancelled	/ / : :	Cancelled	/ / : :		
Cleared Scene	10 /30/2023 18:00:42	Cleared Scene	10 /30/2023 18:00:44		
In Quarters	/ / : :	In Quarters	/ / : :		
In Service	10 /30/2023 18:00:42	In Service	10 /30/2023 18:00:44		
Unit	S282	Unit	POV		
Type:	Support apparatus, other	Туре:	Privately owned vehicle		
Use:	Other	Use:	Other		
Response Mode:	Lights and Sirens	Response Mode:	No Lights or Sirens		
# of People	3	# of People	2		
Alarm	10 /30/2023 15:10:15	Alarm	10 /30/2023 15:10:15		
Dispatched	10 /30/2023 15:11:15	Dispatched	10 /30/2023 15:11:15		
Enroute	10 /30/2023 15:31:04	Enroute	10 /30/2023 15:24:32		
Arrived	10 /30/2023 15:34:59	Arrived	10 /30/2023 15:29:59		
Cancelled	/ / : :	Cancelled	- / - / : :		
Cleared Scene	10 /30/2023 18:00:45	Cleared Scene	10 /30/2023 18:00:45		
In Quarters	/ / : :	In Quarters	/ / : :		
In Service	10 /30/2023 18:00:45	In Service	10 /30/2023 18:00:45		

PAYROLL			• • •	
Name	ID	Points	Pay Grade	
Bain, Matthew R	0439mb02	1	DEFAULT - \$0.00	
Blackmon, Ashlin	5803ac02	1	DEFAULT - \$0.00	
Bond, Steve	4229sb02	1	DEFAULT - \$0.00	
Brown, Joseph M	5279jb02	1	Flat Rate Pay-Per-Call - \$5.50	
Davis, Carlton	3000cd02	1	DEFAULT - \$0.00	
Hair, Christy	4123ci02	1	DEFAULT - \$0.00	
Hanway, Ashton M	6235ah02	1	DEFAULT - \$0.00	
Howe, Alexis L	4623ah02	1	Flat Rate Pay-Per-Call - \$5.50	
Howe, Kasey	8077kh02	1	Flat Rate Pay-Per-Call - \$5.50	
Howe, Therene C	8287th02	1	Flat Rate Pay-Per-Call - \$5.50	
Nordan, Brandon F	4097bn02	1	Flat Rate Pay-Per-Call - \$5.50	
Parr, Robert	4452rp02	1	Flat Rate Pay-Per-Call - \$5.50	
Parr, Thomas	2542tp02	1	Flat Rate Pay-Per-Call - \$5.50	
Watts, Bill	6229bw02	1	DEFAULT - \$0.00	
Wilson, Dustin	0893dw02	1	Flat Rate Pay-Per-Call - \$5.50	
Winpegler, Kurt R	7689kw02	1	Flat Rate Pay-Per-Call - \$5.50	

Member Making Report (Operations Chief Kurt R Winpeg	er):
Incident Reviewer (Operations Chief Kurt R Winpegler):	