

October 30th, 2024

Jonathan Parker
209 Hicks Rd
Broadway, NC 27505

Re: Status of Permit Application-BRES2410-0005

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

1. Use pink flags to mark property lines, survey irons to be located and demonstrated. Property lines marked/flagged every 50'. (25.00 Fee Incurred)

2. House Box needs to be marked/demonstrated. (25.00 Fee Incurred)

3. Directions not clear to property (\$25.00 fee incurred)

4. Clear Vegetation. Do not disturb the soil.

5. Driveway not shown on site plan

6. Backhoe Pits Required

7. Other- House box needs to be rotated and uphill slightly to be 5' off the Environmental Health flags. Site plan must be updated with new house box location and setbacks.

Your application will be put on hold until the selected items above have been addressed.

When completed **please call 910-893-7525 ext. 2 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Mark Osborne R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

MO/kh
Copy: Central Permitting