



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

10/28/2025

SUBJECT: **BRES2503-0037**
BUILDING RESIDENTIAL

To: SWIECA SCOTT LEONARD

Here are the results of all Inspections located at **6745 OLD US 421:**

Inspection Type: ADDRESS
Scheduled Date/Time:
Completed Date/Time:
Inspector: GIS Bucket
Result:
Remarks:
Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: MONO SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 6/27/2025
Completed Date/Time: 6/27/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks:
Notes: Need. Compaction test for footing. Put screening and footing are not to virgin soil.

Inspection Type: FOOTING
Scheduled Date/Time: 7/2/2025
Completed Date/Time: 7/2/2025
Inspector: Daniel L Floyd
Result: APPROVED
Remarks:
Notes: Screenings have been dug out of the footings

Inspection Type: MONO SLAB
Scheduled Date/Time: 7/2/2025
Completed Date/Time: 7/2/2025
Inspector: Daniel L Floyd
Result: APPROVED
Remarks:
Notes:



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: FINAL**
Scheduled Date/Time: 10/7/2025
Completed Date/Time: 10/7/2025
Inspector: Kory S Denny
Result: DISAPPROVED
Remarks:
Notes: Arrived at 12:10 No answer at door.

Inspection Type: FINAL**
Scheduled Date/Time: 10/9/2025
Completed Date/Time: 10/9/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks:
Notes: The building is unlocked and inspector has permission to enter
Need bolts within 6" from every support post per plans
Need bolts within 6" from every support post per plans