PREPARED 7/01/10, 14:20:46 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 7/02/10 . : 34 HENRY RIFLE LN ADDRESS SUBDIV: HUNTERS POINT 45 LOTS CONTRACTOR : PHONE : OWNER . . : LOCKHART ROBERT AND KELLY PHONE: (910) 893-5063 PARCEL . . : 07-0691- - -0023- -18-APPL NUMBER: 09-50022251 CP ADD & ALTER RESIDENTIAL DIRECTIONS: HWY 27 TO CAOTS LEFT ON 55 2ND RD ON RIGHT SILSD HAYES 2ND ENTRANCE TO HUNTERS PIONT TURN RIGHT THEN RIGHT ON WEATHERBY AND LEFT ON HENRY RIFLE ONLY HOUSE ON RIGHT JB STRUCTURE: 000 000 20X14 DECK ADD / ROOF ADD FOR EXS 10X12 FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE : BARN SEPTIC - EXISTING? . . . : EXS WATER SUPPLY : COUNTY PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ

7/02/10 **TI**

REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS

TWO TRADE FINAL VRU #: 001946409

77/0 DABS ALREADY BUILT

Violation Notice Do Not Remove

Harnett County Inspection Tement 102 East Front St P.O. Box 65 Lillington, NC 27546 Phone (910) 893-4876 Fax (910) 893-2793

App #09-50022251 34 Henry Rifle Ln Robert and Kelly Lockhart

- 1. Nail or screw plate supporting rafter either side of each rafter into existing house framing.
- 2. Exterior band on deck supporting floor joists must be a double
- 3. Bolt band at house supporting floor joists per attached (from Code)

Code Enforceme	nt Official	
Ciamatura		
Signature		

PREPARED 7/20/10, 14:12:08 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 7/21/10 ADDRESS : 34 HENRY RIFLE LN SUBDIV: HUNTERS POINT 45 LOTS CONTRACTOR : PHONE : OWNER . . : LOCKHART ROBERT AND KELLY PHONE: (910) 893-5063 PARCEL . . : 07-0691- - -0023- -18-APPL NUMBER: 09-50022251 CP ADD & ALTER RESIDENTIAL DIRECTIONS: HWY 27 TO CAOTS LEFT ON 55 2ND RD ON RIGHT SILSD HAYES 2ND ENTRANCE TO HUNTERS PIONT TURN RIGHT THEN RIGHT ON

STRUCTURE: 000 000 20X14 DECK ADD / ROOF ADD FOR EXS 10X12

WEATHERBY AND LEFT ON HENRY RIFLE ONLY

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE : BARN SEPTIC - EXISTING? : EXS

WATER SUPPLY COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

REOUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT

HOUSE ON RIGHT JB

RESULTS/COMMENTS

R229 01 7/02/10 TWO TRADE FINAL VRU #: 001946409 7/02/10 ALREADY BUILT

> 1 Nail or screw plate supporting rafters either side of each rafter into existing house framing. 2. Exterior band on deck supporting floor joist must be double, also interior girders.3 Bolt band to foundation at house end supporting floor joists T/S: July 02, 2010 02:36 PM

BSUTTON -----

R329 01 7/21/10 ΤI 7/20/10 CA THREE TRADE FINAL VRU #: 001956798

VOICE MESSAGE LEFT

T/S: 07/20/2010 02:11 PM NTART -----

R229 02 7/21/10 TWO TRADE FINAL TIME: 17:00 VRU #: 001957315

T/S: 07/20/2010 02:11 PM NTART ------

