

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Garage

Name: Sonja Belkinger

Address: 900 NC 27 E

Permit Numbers

Building: 17-30041295

Electrical: _____

Insulation: _____


Plumbing: _____

Mechanical: _____

MFG Home: _____

Date: 9/13/2017

Building Official: _____



ADDRESS : 900 NC 27 E
CONTRACTOR :
OWNER : BETTINGER SONJA E
PARCEL : 07-0692- - -0171- -05-
APPL NUMBER: 17-50041295 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : T/S: 05/03/2017 10:41 AM JBROCK ----
900 NC 27 E

SUBDIV:
PHONE :
PHONE :

STRUCTURE: 000 000 26X36 ATTACHED GARAGE

FLOOD ZONE : FLOOD ZONE X
SEPTIC - EXISTING? : EXT TANK
WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/17/17	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002972894
	5/17/17	AP	T/S: 05/17/2017 12:51 PM DETAYLOR -----
B103 01	5/31/17	JLP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002978273
	5/31/17	DA	1) Clean off footings for projection inspection on both sides. 2)Remove excess block inside foundation wall. Can not use for fill.
B103 02	6/02/17	JLP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002979236
	6/02/17	DA	Must have two inch projection each side.
B103 03	6/06/17	JLP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002980377
	6/06/17	AP	T/S: 06/06/2017 01:22 PM JPERRY -----
R125 01	6/26/17	DT	ONE TRADE ROUGH IN VRU #: 002988823
	6/26/17	DA	T/S: 06/26/2017 04:33 PM DETAYLOR ----- Schedule electrical rough in Need complete set of truss documents Truss hangers missing nails, and short nails must be replaced (3 inch required)
R225 01	6/29/17	BS	TWO TRADE ROUGH IN VRU #: 002990730
	6/29/17	DA	T/S: June 29, 2017 01:47 PM BSUTTON ----- Firestop all holes top and bottom plate in walls that will have sheetrock. 2. Foundation vents will have to be closed before final. 3. Panel must have a permanent tag inside that denotes all circuits with 12 wire homerun to 14 wire circuits that they are to be on a 15 amp breaker max.
R125 02	7/07/17	JLP	ONE TRADE ROUGH IN VRU #: 002993540
	7/07/17	AP	T/S: 07/07/2017 02:37 PM JPERRY -----
R229 01	7/25/17	DT	TWO TRADE FINAL VRU #: 003002262
	7/25/17	DA	T/S: 07/25/2017 11:07 AM DETAYLOR ----- Door from garage to house must be sealed Repair holes in sheetrock
R229 02	8/28/17	JLP	TWO TRADE FINAL TIME: 17:00 VRU #: 003017522
	8/28/17	DA	T/S: 08/25/2017 10:36 AM DJOHNSON ----- CUSTOMER CALLED SAYING THAT HIS PERMIT WAS GONE OUT OF BOX. I TOLD HIM IT WAS OK I WOULD STILL PUT HIM ON FOR A FINAL. IF THIS IS A PROBLEM FOR THE FINAL PLEASE LET ME KNOW AND I WILL REPRINT PERMIT FOR YOU. Door from garage to house must be sealed
R229 03	8/30/17	DT	TWO TRADE FINAL TIME: 17:00 VRU #: 003018587
	8/30/17	DA	T/S: 08/29/2017 09:16 AM BPETRICH ----- T/S: 08/30/2017 03:51 PM DETAYLOR ----- Garage ceiling must be sheetrocked for fire separation

ADDRESS . . : 900 NC 27 E SUBDIV:
CONTRACTOR : PHONE :
OWNER . . . : BETTINGER SONJA E PHONE :
PARCEL . . . : 07-0692- - -0171- -05-
APPL NUMBER: 17-50041295 CP ADD & ALTER RESIDENTIAL

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R225 02	9/13/17 <u>9/13/17</u>	TI <u>AP P</u>	TWO TRADE ROUGH IN VOICE MESSAGE LEFT VRU #: 003023980

----- COMMENTS AND NOTES -----