



Harnett County Government Complex
307 Cornelius Harnett Boulevard
Lillington, NC 27546

ph: 910-893-7547
fax: 910-893-9371

February 11, 2011

Overhills Community Baptist Church
948 Overhills Rd.
Linden, N.C. 28356

RE: Existing Septic System Inspection HTE # 10-5-25814


To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover the outlet lid on septic tank and break seal – (\$25.00 fee incurred)
- 2. Have system pumped out
- 3. Replace sanitary T
- 4. Other- Filter needs to be reinstalled. Broken pipe between septic tank and pump tank needs to be repaired and inspected.

Your application will be put on hold until the selected items above have been addressed. When completed call 910-893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation. You can reach me between the hours of 8-9:00 a.m.

Sincerely,


Oliver Tolksdorf, R.E.H.S.
Environmental Health Soil Scientist
Harnett County Department of Public Health
Environmental Health

OT/sez
Copy - Central Permitting



Harnett County Government Complex
307 Cornelius Harnett Boulevard
Lillington, NC 27546

ph: 910-893-7550

fax: 910-893-9429

March 2, 2009

Overhills Baptist Church
PO Box 1015
Lillington, NC 27546

On a recent site visit to inspect your septic system I observed your septic system drain field being disked by a tractor. Upon further investigation remnants of the valve boxes were discovered and the valves for the manatee were not able to be found. Severe damage may have been caused by the actions taken on your drain field. In order determine the extent of the damage the Harnett County Health Department will revisit your site after you have located the four valves associated with your system. Please contact me at 893-7547 when you have located these valves so I can reinspect your system and determine what repairs, if any, need to take place. Thank you for your attention to this matter.

Sincerely,

Oliver Tolksdorf RS
Soil Scientist