

Harnett County Government Complex  
307 W. Cornelius Harnett Boulevard  
Lillington, NC 27546

ph: 910-893-7547  
fax: 910-893-9371

July 12, 2017

Joe Gregory  
2812 Carson Gregory Rd  
Angier, NC 27501

**RE: New Well Application Inspection HTE# 17-5-41759**

Mr. Gregory

An attempt was made to evaluate your property for the purpose of issuing a Well Permit. The evaluation could not be completed for one or more of the following reasons.

1. Uncover outlet lid on septic tank and break seal. (\$25.00 fee incurred)  
15A NCAC 02C.0107(2) (A)

2. Have system pumped out

3. Replace sanitary T

4. Other

Your application will be put on hold until the selected items above have been addressed. **A minimum horizontal setback between a water supply well and septic tank and drain field of 100ft must be verified to safeguard the public welfare, safety, health, and to protect and beneficially develop groundwater resources of the state (15A NCAC 02C.0107(2) (A)).**

When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S  
Environmental Health OSWW Scientist  
Harnett County Department of Public Health  
Environmental Health

AC/kh  
Copy - Central Permitting