

2/05

THE SYSTEM AREA ON LOT 35 WAS DISTURBED. IT WAS DRIVEN OVER BY CONSTRUCTION TRAFFIC. SEVERAL HOLES WERE DUG TO VERIFY THAT SOIL WAS NOT REMOVED. THE TIRE TRACKS (RIMS) WERE LEVELED AND TRENCH DEPTH ADJUSTED TO ACCOUNT FOR THE SITE DISTURBANCE.