
ADDRESS . . : 10 BELMONT CT SUBDIV: COLONIAL HILLS
CONTRACTOR : BECKER CONST LLC PHONE : (910) 263-2700
OWNER . . . : DENARLA ENTERPRISES #62 PHONE :
PARCEL . . . : 03-0507- - -0226- -80-
APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS #62
210 RIGHT ON RAY RD RIGHT ON NURSERY RD
LEFT ON DOCS RD 1MILE ON LEFT
T/S: 09/04/2007 01:14 PM JBROCK -----

STRUCTURE: 000 000 50X50 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|------------------------|----------------|---|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| A814 01 | 10/03/07 | TI | ADDRESS CONFIRMATION VRU #: 001497585 |
| B103 01 | 10/03/07 | TI | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | <u>10/3/07</u> | <u>AE DT</u> | |

----- COMMENTS AND NOTES -----

ADDRESS . : 10 TORY CT SUBDIV: COLONIAL HILLS
CONTRACTOR : BECKER CHAD WILLIAM PHONE : (910) 263-2612
OWNER . . : DENARLA ENTERPRISES #62 PHONE :
PARCEL . . : 03-0507- - -0226- -80-
APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS #62
210 RIGHT ON RAY RD RIGHT ON NURSERY RD
LEFT ON DOCS RD 1MILE ON LEFT
T/S: 09/04/2007 01:14 PM JBROCK -----

STRUCTURE: 000 000 50X50 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|------------------------|----------------|---|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| B103 01 | 10/03/07 | DT | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | 10/03/07 | AE | 1. Pier circled on plans must be shifted to the right to be in center third of footer. Okay to put floor system on. |
| A814 01 | 10/03/07 | TI | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001497585 |
| | 10/02/07 | AP | 10 Tory Ct Lot 62 |
| B105 01 | 10/09/07 | TI | R*OPEN FLOOR VRU #: 001501220 |
| | 10/09/07 | CA | WOULD LIKE THIS AFTERNOON. ***** |
| B105 02 | 10/10/07 | MR | R*OPEN FLOOR VRU #: 001502319 |
| | 10/10/07 | AP | |
| R425 01 | 11/08/07 | TI | FOUR TRADE ROUGH IN VRU #: 001517960 |
| | <u>11/8/07</u> | <u>DA DT</u> | |

----- COMMENTS AND NOTES -----

ADDRESS : 10 TORY CT
CONTRACTOR : BECKER CHAD WILLIAM
OWNER : DENARLA ENTERPRISES #62
PARCEL : 03-0507- - -0226- -80-
APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS #62
210 RIGHT ON RAY RD RIGHT ON NURSERY RD
LEFT ON DOCS RD 1MILE ON LEFT
T/S: 09/04/2007 01:14 PM JBROCK ----

SUBDIV: COLONIAL HILLS
PHONE : (910) 263-2612
PHONE :

STRUCTURE: 000 000 50X50 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|------------------------|----------------|--|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| B103 01 | 10/03/07 | DT | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | 10/03/07 | AE | 1. Pier circled on plans must be shifted to the right to be in center third of footer. Okay to put floor system on. |
| A814 01 | 10/03/07 | TI | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001497585 |
| | 10/02/07 | AP | 10 Tory Ct Lot 62 |
| B105 01 | 10/09/07 | TI | R*OPEN FLOOR VRU #: 001501220 |
| | 10/09/07 | CA | WOULD LIKE THIS AFTERNOON. ***** |
| B105 02 | 10/10/07 | MR | R*OPEN FLOOR VRU #: 001502319 |
| | 10/10/07 | AP | |
| R425 01 | 11/08/07 | DT | FOUR TRADE ROUGH IN VRU #: 001517960 |
| | 11/08/07 | DA | <input checked="" type="checkbox"/> No water in stand pipe. <input checked="" type="checkbox"/> No water test for master shower. <input checked="" type="checkbox"/> Fire caulk holes for electrical at top plate to right of front door and between family room and master bathroom. <input checked="" type="checkbox"/> Caulk holes for master tub water lines and holes at bottom plate in hallway closet by bedroom 3. <input checked="" type="checkbox"/> No fireplace or gas pressure. |
| R425 02 | 11/09/07 | TI | FOUR TRADE ROUGH IN VRU #: 001518463 |
| | | AP JH | |

----- COMMENTS AND NOTES -----

ADDRESS . . : 10 TORY CT SUBDIV: COLONIAL HILLS
CONTRACTOR : BECKER CHAD WILLIAM PHONE : (910) 263-2612
OWNER . . : DENARLA ENTERPRISES #62 PHONE :
PARCEL . . : 03-0507- - -0226- -80-
APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS #62
210 RIGHT ON RAY RD RIGHT ON NURSERY RD
LEFT ON DOCS RD 1MILE ON LEFT
T/S: 09/04/2007 01:14 PM JBROCK ----

STRUCTURE: 000 000 50X50 3BR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|------------------------|----------------|---|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| B103 01 | 10/03/07 | DT | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | 10/03/07 | AE | 1. Pier circled on plans must be shifted to the right to be in center third of footer. Okay to put floor system on. |
| A814 01 | 10/03/07 | TI | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001497585 |
| | 10/02/07 | AP | 10 Tory Ct Lot 62 |
| B105 01 | 10/09/07 | TI | R*OPEN FLOOR VRU #: 001501220 |
| | 10/09/07 | CA | WOULD LIKE THIS AFTERNOON. ***** |
| B105 02 | 10/10/07 | MR | R*OPEN FLOOR VRU #: 001502319 |
| | 10/10/07 | AP | |
| R425 01 | 11/08/07 | DT | FOUR TRADE ROUGH IN VRU #: 001517960 |
| | 11/08/07 | DA | 1. No water in stand pipe. 2. No water test for master shower. 3. Fire caulk holes for electrical at top plate to right of front door and between family room and master bathroom. 4. Caulk holes for master tub water lines and holes at bottom plate in hallway closet by bedroom 3. 5. No fireplace or gas pressure. |
| R425 02 | 11/09/07 | JH | FOUR TRADE ROUGH IN VRU #: 001518463 |
| | 11/09/07 | AP | |
| I129 01 | 11/14/07 | TI | R*INSULATION INSPECTION VRU #: 001519883 |
| | <u>11/14/07</u> | <u>AP DT</u> | |

----- COMMENTS AND NOTES -----

INSPECTION TICKET
INSPECTOR: IVR

PREPARED 1/29/09, 13:59:08
Harnett County

SUBDIV: COLONIAL HILLS
PHONE: (910) 263-2612
PHONE:

ADDRESS : 10 TORY CT
CONTRACTOR : BECKER CHAD WILLIAM
OWNER : DENARLA ENTERPRISES #62
PARCEL : 03-0507-0226-80-
APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS #62
210 RIGHT ON RAY RD RIGHT ON NURSERY RD
LEFT ON DOCS RD 1MILE ON LEFT
T/S: 09/04/2007 01:14 PM JBROCK

PROPOSED USE : SFD

STRUCTURE: 000 000 50X50 3BR
FLOOD ZONE : FLOOD ZONE X 3.00
BEDROOMS : NEW

PERMIT: CPSF 00 CP * SFD
REQUESTED INSP
COMPLETED RESULT

| TYP/SQ | REQUESTED | INSP | DESCRIPTION |
|---------|-----------|------|---|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| B103 01 | 10/03/07 | DT | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | 10/03/07 | AE | Okay to put floor system on. VRU #: 001497593 |
| | | | ADDRESS CONFIRMATION Lot 62 VRU #: 001497593 |
| | | | WOULD LIKE THIS AFTERNOON. TIME: 17:00 VRU #: 001497593 |
| | | | R*OPEN FLOOR VRU #: 001501220 |
| | | | R*OPEN FLOOR VRU #: 001502319 |
| A814 01 | 10/03/07 | TI | FOUR TRADE ROUGH IN VRU #: 001517960 |
| | 10/02/07 | AP | 1. No water in stand pipe. |
| B105 01 | 10/09/07 | TI | 2. No water test for master shower. |
| | 10/09/07 | CA | 3. Fire door and between family room |
| B105 02 | 10/10/07 | MR | front door and between master tub wat |
| | 10/10/07 | AP | 4. Caulk holes for master closet b |
| | 10/10/07 | DT | bottom plate in hallway closet b |
| R425 01 | 11/08/07 | DA | 5. No fireplace or gas pressur |
| | 11/08/07 | | FOUR TRADE ROUGH IN VRU #: |
| | | | R*INSULATION INSPECTION |
| | | | ENVIR. OPERATIONS PERMI |
| | | | FOUR TRADE FINAL T |

| | | |
|---------|----------|----|
| R425 02 | 11/09/07 | JH |
| | 11/09/07 | AP |
| I129 01 | 11/14/07 | DT |
| | 11/14/07 | AP |
| H824 01 | 1/09/08 | JW |
| | 1/09/08 | AP |
| R429 01 | 1/30/09 | TI |

DATE

COMMENTS 7

OK Exit

ADDRESS : 10 TORY CT SUBDIV: COLONIAL HILLS
 CONTRACTOR : BECKER CHAD WILLIAM PHONE : (910) 263-2612
 OWNER : DENARLA ENTERPRISES #62 PHONE :
 PARCEL : 03-0507- - -0226- -80-
 APPL NUMBER: 06-50016034 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : COLONIAL HILLS #62
 210 RIGHT ON RAY RD RIGHT ON NURSERY RD
 LEFT ON DOCS RD 1MILE ON LEFT
 T/S: 09/04/2007 01:14 PM JBROCK ----

STRUCTURE: 000 000 50X50 3BR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|---------------------|-------------|---|
| B101 01 | 9/24/07 | DT | R*BLDG FOOTING / TEMP SVC POLE VRU #: 001491935 |
| | 9/24/07 | AP | PLEASE INSPECT THE TSP. |
| B103 01 | 10/03/07 | DT | R*BLDG FOUND & TEMP SVC POLE VRU #: 001497593 |
| | 10/03/07 | AE | 1. Pier circled on plans must be shifted to the right to be in center third of footer. Okay to put floor system on. |
| A814 01 | 10/03/07 | TI | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001497585 |
| | 10/02/07 | AP | ✓ 10 Tory Ct Lot 62 |
| B105 01 | 10/09/07 | TI | R*OPEN FLOOR VRU #: 001501220 |
| | 10/09/07 | CA | WOULD LIKE THIS AFTERNOON. ***** |
| B105 02 | 10/10/07 | MR | R*OPEN FLOOR VRU #: 001502319 |
| | 10/10/07 | AP | |
| R425 01 | 11/08/07 | DT | FOUR TRADE ROUGH IN VRU #: 001517960 |
| | 11/08/07 | DA | 1. No water in stand pipe. 2. No water test for master shower. 3. Fire caulk holes for electrical at top plate to right of front door and between family room and master bathroom. 4. Caulk holes for master tub water lines and holes at bottom plate in hallway closet by bedroom 3. 5. No fireplace or gas pressure. |
| R425 02 | 11/09/07 | JH | FOUR TRADE ROUGH IN VRU #: 001518463 |
| | 11/09/07 | AP | |
| I129 01 | 11/14/07 | DT | R*INSULATION INSPECTION VRU #: 001519883 |
| | 11/14/07 | AP | ✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001545961 |
| H824 01 | 1/09/08 | JW | |
| | 1/09/08 | AP | |
| R429 01 | 1/30/09 | DT | FOUR TRADE FINAL TIME: 17:00 VRU #: 001729615 |
| | 1/30/09 | DA | 1. No house numbers. 2. Washer drain must be 34 inches from floor. 3. No vapor barrier in crawl space. |
| R429 02 | 2/02/09 | TI | FOUR TRADE FINAL TIME: 17:00 VRU #: 001730795 |
| | 2/2/09 | AP DT | |

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Owner: William Becker

911 Address: 10 Tory Ct.

State: NC Zip Code: _____

Date: 2/2/09

D. E. T. R. E.
Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

MFG. Home: _____

06-50016034