
ADDRESS . . : 135 SHERMAN PINES DR SUBDIV: SHERMAN PINES
CONTRACTOR : HAMILTON JERRY PHONE : (910) 893-4751
OWNER . . . : HAMILTON BUILDERS #4 PHONE : (910) 893-8427
PARCEL . . . : 08-0655- - -0118- -40-
APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SHERMAN PINES #4
401N 10MILES LEFT INTO SHERMAN PINES
LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 56X72 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	<u>3-15-07</u>	<u>APBS</u>	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	135 sherman pines dr

----- COMMENTS AND NOTES -----

ADDRESS . : 135 SHERMAN PINES DR SUBDIV: SHERMAN PINES
CONTRACTOR : HAMILTON JERRY PHONE : (910) 893-4751
OWNER . . : HAMILTON BUILDERS #4 PHONE : (910) 893-8427
PARCEL . . : 08-0655- - -0118- -40-
APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SHERMAN PINES #4
401N 10MILES LEFT INTO SHERMAN PINES
LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 56X72 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	3/15/07	AP	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	135 sherman pines dr
B105 01	3/20/07	TI	R*OPEN FLOOR VRU #: 001373999
	<u>3/20/07</u>	<u>APBS</u>	

----- COMMENTS AND NOTES -----

919-559-1499

ADDRESS . . : 135 SHERMAN PINES DR SUBDIV: SHERMAN PINES
CONTRACTOR : HAMILTON JERRY PHONE : (910) 893-4751
OWNER . . . : HAMILTON BUILDERS #4 PHONE : (910) 893-8427
PARCEL . . . : 08-0655- - -0118- -40-
APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SHERMAN PINES #4
401N 10MILES LEFT INTO SHERMAN PINES
LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 56X72 3BR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	3/15/07	AP	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	135 sherman pines dr
B105 01	3/20/07	BS	R*OPEN FLOOR VRU #: 001373999
	3/20/07	AP	
R427 01	4/18/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001391602
	<u>4-18-07</u>	<u>DABS</u>	

----- COMMENTS AND NOTES -----

2018
2237

ADDRESS : 135 SHERMAN PINES DR SUBDIV: SHERMAN PINES
 CONTRACTOR : HAMILTON JERRY PHONE : (910) 893-4751
 OWNER : HAMILTON BUILDERS #4 PHONE : (910) 893-8427
 PARCEL : 08-0655- - -0118- -40-
 APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SHERMAN PINES #4
 401N 10MILES LEFT INTO SHERMAN PINES
 LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 56X72 3BR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	3/15/07	AP	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	135 sherman pines dr
B105 01	3/20/07	BS	R*OPEN FLOOR VRU #: 001373999
	3/20/07	AP	
R427 01	4/18/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001391602
	4/18/07	DA	1. Brace kneewall above kitchen LVL carrying roof span (in attic) 2. Check headroom in stairway at LVL valley. Must have 6'8 " in ALL portions of the stairway, and it must be measured in the stair run, not from the stair tread. We write this up now, in case it is an issue at final. 3. Plan shows a double 9.25 LVL over windows beside fireplace 4. AT LVL valley above front door, block and jack all the way down to bottom plate for support. OK TO SIDE, INSULATE
I129 01	4/20/07	TI	R*INSULATION INSPECTION VRU #: 001393370
	<u>4.20.07</u>	<u>APRS</u>	
R127 01	4/20/07	TI	ONE TRADE ROUGH IN > 2500 VRU #: 001393361
	<u>4/20/07</u>	<u>TI</u>	

COMMENTS AND NOTES

ADDRESS : 135 SHERMAN PINES DR SUBDIV: SHERMAN PINES
CONTRACTOR : HAMILTON JERRY PHONE : (910) 893-4751
OWNER : HAMILTON BUILDERS #4 PHONE : (910) 893-8427
PARCEL : 08-0655- - -0118- -40-
APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SHERMAN PINES #4
401N 10MILES LEFT INTO SHERMAN PINES
LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 56X72 3BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	3/15/07	AP	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	✓ 135 sherman pines dr
B105 01	3/20/07	BS	R*OPEN FLOOR VRU #: 001373999
	3/20/07	AP	
R427 01	4/18/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001391602
	4/18/07	DA	1. Brace kneewall above kitchen LVL carrying roof span (in attic) 2. Check headroom in stairway at LVL valley. Must have 6'8 " in ALL portions of the stairway, and it must be measured in the stair run, not from the stair tread. We write this up now, in case it is an issue at final. 3. Plan shows a double 9.25 LVL over windows beside fireplace 4. AT LVL valley above front door, block and jack all the way down to bottom plate for support. OK TO SIDE, INSULATE
I129 01	4/20/07	BS	R*INSULATION INSPECTION VRU #: 001393370
	4/20/07	AP	
R127 01	4/20/07	BS	ONE TRADE ROUGH IN > 2500 VRU #: 001393361
	4/20/07	AP	
H824 01	5/02/07	JM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001402957
	5/02/07	AP	
R431 01	6/05/07	TI	FOUR TRADE FINAL >2500 VRU #: 001422437

6-5-07 DABS

COMMENTS AND NOTES

ADDRESS : 135 SHERMAN PINES DR
 CONTRACTOR : HAMILTON JERRY
 OWNER : HAMILTON BUILDERS #4
 PARCEL : 08-0655- - -0118- -40-
 APPL NUMBER: 07-50016477 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SHERMAN PINES #4
 401N 10MILES LEFT INTO SHERMAN PINES
 LOT ON LEFT. JDAVIS

SUBDIV: SHERMAN PINES
 PHONE : (910) 893-4751
 PHONE : (910) 893-8427

STRUCTURE: 000 000 56X72 3BR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/06/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001365702
	3/06/07	AP	
B103 01	3/15/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370545
	3/15/07	AP	
A814 01	3/15/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001369218
	3/12/07	AP	✓135 sherman pines dr
B105 01	3/20/07	BS	R*OPEN FLOOR VRU #: 001373999
	3/20/07	AP	
R427 01	4/18/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001391602
	4/18/07	DA	1. Brace kneewall above kitchen LVL carrying roof span (in attic) 2. Check headroom in stairway at LVL valley. Must have 6'8 " in ALL portions of the stairway, and it must be measured in the stair run, not from the stair tread. We write this up now, in case it is an issue at final. 3. Plan shows a double 9.25 LVL over windows beside fireplace 4. AT LVL valley above front door, block and jack all the way down to bottom plate for support. OK TO SIDE, INSULATE
I129 01	4/20/07	BS	R*INSULATION INSPECTION VRU #: 001393370
	4/20/07	AP	
R127 01	4/20/07	BS	ONE TRADE ROUGH IN > 2500 VRU #: 001393361
	4/20/07	AP	
H824 01	5/02/07	JM	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001402957
	5/02/07	AP	
R431 01	6/05/07	BS	FOUR TRADE FINAL >2500 VRU #: 001422437
	6/05/07	DA	1. Close up cantilever under deck w/ vinyl or plywood (painted or treated) 2. Seal unused drain holes in unit under house and seal around lineset at unit. 3. Caulk toilet in upstairs bath. Reschedule/no fee
R431 02	6/07/07	TI	FOUR TRADE FINAL >2500 VRU #: 001424168

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Type of Construction: II

Owner of Building: Hamilton Builders

Building Address: 135 Skuman Acres

Zoning District: _____

Zoning Permit No.: NA

Date: 6-7-07

Brad Sitter

Building Official

Conditional Use Permit No.: _____

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: 07-5-16477

Envir. C.O. No.: _____

Zoning Official