

PREPARED 2/26/07, 14:00:08  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 65  
DATE 2/27/07

-----  
ADDRESS . : 171 BENDAMOORE CT  
CONTRACTOR : CURRIN BUILDERS INC  
OWNER . . : CURRIN BUILDERS INC #25  
PARCEL . . : 08-0653- - -0030- -25-  
APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #25  
401N TO CHALYBEATE RD LEFT TO  
DEXTERFIELD LOT ON RIGHT ON BENDAMOORE  
DR LOT 25 JB

SUBDIV: DEXTERFIELD  
PHONE : (919) 639-6989  
PHONE : (919) 639-6989

-----  
**STRUCTURE: 000 000 58X55 3BR**  
FLOOD ZONE . . . . : FLOOD ZONE X

-----  
**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED	INSP	DESCRIPTION
	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	2/27/07	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
	<u>2-27-07</u>	<u>APBS</u>	

-----  
COMMENTS AND NOTES -----

PREPARED 3/02/07, 13:58:44  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 33  
DATE 3/05/07

-----  
ADDRESS . : 171 BRENDAMOORE CT  
CONTRACTOR : CURRIN BUILDERS INC  
OWNER . . : CURRIN BUILDERS INC #25  
PARCEL . . : 08-0653- - -0030- -25-  
APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #25  
401N TO CHALYBEATE RD LEFT TO  
DEXTERFIELD LOT ON RIGHT ON BRENDAMOORE  
DR LOT 25 JB  
-----

STRUCTURE: 000 000 58X55 3BR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/27/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
B103 01	2/27/07	AP	
	3/05/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001364963
	<u>3-5-07</u>	<u>APBS</u>	

----- COMMENTS AND NOTES -----

-----  
ADDRESS . : 171 BENDAMOORE CT  
CONTRACTOR : CURRIN BUILDERS INC  
OWNER . . : CURRIN BUILDERS INC #25  
PARCEL . . : 08-0653- - -0030- -25-  
APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #25  
401N TO CHALYBEATE RD LEFT TO  
DEXTERFIELD LOT ON RIGHT ON BENDAMOORE  
DR LOT 25 JB  
-----

STRUCTURE: 000 000 58X55 3BR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/27/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
	2/27/07	AP	
B103 01	3/05/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001364963
	3/05/07	AP	have damproofing on at open floor, do not backfill exterior
B105 01	3/21/07	TT	R*OPEN FLOOR VRU #: 001374872
	<u>3-21-07</u>	<u>APBS</u>	

----- COMMENTS AND NOTES -----

-----

ADDRESS . : 171 BENDAMOORE CT SUBDIV: DEXTERFIELD  
 CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989  
 OWNER . . : CURRIN BUILDERS INC #25 PHONE : (919) 639-6989  
 PARCEL . . : 08-0653- - -0030- -25-  
 APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : DEXTERFIELD #25  
 401N TO CHALYBEATE RD LEFT TO  
 DEXTERFIELD LOT ON RIGHT ON BENDAMOORE  
 DR LOT 25 JB

-----

STRUCTURE: 000 000 58X55 3BR  
 FLOOD ZONE . . . . : FLOOD ZONE X

-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/27/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
	2/27/07	AP	
B103 01	3/05/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001364963
	3/05/07	AP	have damproofing on at open floor, do not backfill exterior
B105 01	3/21/07	BS	R*OPEN FLOOR VRU #: 001374872
	3/21/07	AP	
R425 01	4/23/07	BS	FOUR TRADE ROUGH IN VRU #: 001394976
	4/23/07	CA	per contractor
R425 02	4/24/07	TI	FOUR TRADE ROUGH IN VRU #: 001395886
	<u>4-24-07</u>	<u>DA3</u>	
A814 01	4/24/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001392736
	4/20/07	AP	171 Brendamoore Ct Lot 25

----- COMMENTS AND NOTES -----

-----  
ADDRESS . : 171 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989  
OWNER . . : CURRIN BUILDERS INC #25 PHONE : (919) 639-6989  
PARCEL . . : 08-0653- - -0030- -25-  
APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
-----

DIRECTIONS : DEXTERFIELD #25  
401N TO CHALYBEATE RD LEFT TO  
DEXTERFIELD LOT ON RIGHT ON BRENDAMOORE  
DR LOT 25 JB  
-----

STRUCTURE: 000 000 58X55 3BR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/27/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
	2/27/07	AP	
B103 01	3/05/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001364963
	3/05/07	AP	have damproofing on at open floor, do not backfill exterior
B105 01	3/21/07	BS	R*OPEN FLOOR VRU #: 001374872
	3/21/07	AP	
R425 01	4/23/07	BS	FOUR TRADE ROUGH IN VRU #: 001394976
	4/23/07	CA	per contractor
R425 02	4/24/07	BS	FOUR TRADE ROUGH IN VRU #: 001395886
	4/24/07	DA	1. Shim all jack studs that are not tight to their headers. 2. Need hangers or supprts at deck to cantilever. 3. Sheet inside garage walls w/ OSB
A814 01	4/24/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001392736
	4/20/07	AP	171 Brendamoore Ct Lot 25
I129 01	4/26/07	TI	R*INSULATION INSPECTION VRU #: 001398160
	<u>4/26/07</u>	<u>APBS</u>	
R425 03	4/26/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001398395
	<u>4/26/07</u>	<u>TI</u>	

----- COMMENTS AND NOTES -----  
-----

-----  
ADDRESS . : 171 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989  
OWNER . . : CURRIN BUILDERS INC #25 PHONE : (919) 639-6989  
PARCEL . . : 08-0653- - -0030- -25-  
APPL NUMBER: 07-50016806 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #25  
401N TO CHALYBEATE RD LEFT TO  
DEXTERFIELD LOT ON RIGHT ON BRENDAMOORE  
DR LOT 25 JB  
-----

STRUCTURE: 000 000 58X55 3BR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/27/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001361583
	2/27/07	AP	
B103 01	3/05/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001364963
	3/05/07	AP	have damproofing on at open floor, do not backfill exterior
B105 01	3/21/07	BS	R*OPEN FLOOR VRU #: 001374872
	3/21/07	AP	
R425 01	4/23/07	BS	FOUR TRADE ROUGH IN VRU #: 001394976
	4/23/07	CA	per contractor
R425 02	4/24/07	BS	FOUR TRADE ROUGH IN VRU #: 001395886
	4/24/07	DA	1. Shim all jack studs that are not tight to their headers. 2. Need hangers or supprts at deck to cantilever. 3. Sheet inside garage walls w/ OSB
A814 01	4/24/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001392736
	4/20/07	AP	171 Brendamoore Ct Lot 25
I129 01	4/26/07	BS	R*INSULATION INSPECTION VRU #: 001398160
	4/26/07	AP	
R425 03	4/26/07	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001398395
	4/26/07	AP	
H824 01	9/27/07	BM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001495225
	9/27/07	AP	
R429 01	4/11/08	TI	FOUR TRADE FINAL VRU #: 001589282

*AP-ML*

-----  
COMMENTS AND NOTES  
-----

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: R-3

Type of Construction: I

Owner of Building: Curran Bldgs

Building Address: 171 Broadmore

Zoning District: \_\_\_\_\_

Zoning Permit No.: \_\_\_\_\_

Conditional Use Permit No.: \_\_\_\_\_

Building Permit No.: 07-50016806

Electrical Permit No.: '

Insulation Permit No.: '

Plumbing Permit No.: '

Mech. Permit No.: '

Envir. C.O. No.: \_\_\_\_\_

Date: 4-11-8

Mike Ream

Building Official

Zoning Official