

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**   X  

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Stancil Builders Inc

Address: 71 Henry Rifle Ln  
Angier, NC 27501

Date: 4-12-17

Building Official: \_\_\_\_\_

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: 07-50016952

MFG Home: \_\_\_\_\_

*[Handwritten Signature]*

ADDRESS : 71 HENRY RIFLE LN SUBDIV: HUNTERS POINT 45 LOTS  
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073  
 OWNER : STANCIL BUILDERS #16 PHONE :  
 PARCEL : 07-0691- - -0023- -15-  
 APPL NUMBER: 07-50016952 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : HUNTERS POINT #16  
 HWY 27 TO COATS LEFT ON 55 TOWARDS  
 ANGIER, RIGHT ON SILAS HAYES RD SUBD ON  
 RIGHT.  
 T/S: 02/26/2007 11:46 AM DJOHNSON --

STRUCTURE: 000 000 40X60 3 BR  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP \* SFD

| TYP/SQ  | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS   |
|---------|---------------------|-------------|--|
| B101 01 | 9/14/16             | DT          | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002871010  |
|         | 9/14/16             | AP          | T/S: 09/13/2016 12:09 PM LBENNETT -----<br>T/S: 09/14/2016 12:17 PM DETAYLOR -----   |
| A814 01 | 10/07/16            | TW          | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002882132  |
|         | 10/07/16            | AP          | 71 Henry Rifle Ln Angier 27501<br>10/07/2016 11:04 AM TWARD -----<br>T/S: 10/07/2016 11:40 AM TWARD -----  |
| B103 01 | 10/07/16            | DT          | R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002882124  |
|         | 10/07/16            | AP          | T/S: 10/06/2016 12:37 PM DJOHNSON -----<br>T/S: 10/07/2016 04:20 PM DETAYLOR -----   |
| B105 01 | 11/18/16            | DT          | R*OPEN FLOOR TIME: 17:00 VRU #: 002900298  |
|         | 11/18/16            | AP          | T/S: 11/17/2016 01:32 PM JFORBES -----<br>T/S: 11/18/2016 02:11 PM DETAYLOR -----  |
| R425 01 | 12/28/16            | DT          | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002914034   |
|         | 12/28/16            | DA          | T/S: 12/22/2016 09:41 AM JBROCK -----<br>T/S: 12/28/2016 01:08 PM DETAYLOR -----<br>Rafters are not bearing on ridge beam<br>Okay to side and insulate |
| I129 01 | 1/03/17             | DT          | R*INSULATION INSPECTION TIME: 17:00 VRU #: 002915981   |
|         | 1/04/17             | AP          | T/S: 12/30/2016 01:10 PM LBENNETT -----<br>T/S: 01/04/2017 09:16 AM DETAYLOR -----   |
| R425 02 | 1/03/17             | DT          | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002915999   |
|         | 1/04/17             | AP          | T/S: 12/30/2016 01:10 PM LBENNETT -----<br>T/S: 01/04/2017 09:16 AM DETAYLOR -----   |
| B104 01 | 1/10/17             | JB          | R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002918449  |
|         | 1/10/17             | AP          | T/S: 01/10/2017 09:24 AM JBROCK -----  |
| H824 01 | 3/22/17             | OT          | ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002948784  |
|         | 3/22/17             | AP          | T/S: 03/23/2017 11:54 AM KHINSON -----<br>T/S: 03/23/2017 11:54 AM KHINSON -----   |
| R429 01 | 4/12/17             | TI          | FOUR TRADE FINAL VRU #: 002957562  |
|         | <u>4/22/17</u>      | <u>APDT</u> |  |

COMMENTS AND NOTES