

-----  
ADDRESS . . : 158 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : PHONE :  
OWNER . . . : ATKINS PLACE LLC #30 PHONE :  
PARCEL . . . : 08-0653- - -0030- -30-  
APPL NUMBER: 07-50016992 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D  
IS 1/4 MILE ON LEFT LOT 30 JB  
-----

STRUCTURE: 000 000 40X80 3BDR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/21/08	TI <u>AP-MP</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001566380

----- COMMENTS AND NOTES -----

Temp OK  
Prew# ?

-----  
ADDRESS . : 158 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : PHONE :  
OWNER . . : ATKINS PLACE LLC #30 PHONE :  
PARCEL . . : 08-0653- - -0030- -30-  
APPL NUMBER: 07-50016992 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D  
IS 1/4 MILE ON LEFT LOT 30 JB  
\*\*\*\*\*PREMISE NUMBER 30626912\*\*\*\*\*  
-----

STRUCTURE: 000 000 40X80 3BDR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/21/08 2/21/08	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001566380
A814 01	3/19/08	TI	ADDRESS CONFIRMATION VRU #: 001579424
B103 01	<u>3/19/08</u> <u>3-19-08</u>	<u>TI</u> <u>ADBS</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001579440

----- COMMENTS AND NOTES -----  
-----

-----  
ADDRESS . : 158 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : PHONE :  
OWNER . . : ATKINS PLACE LLC #30 PHONE :  
PARCEL . . : 08-0653- - -0030- -30-  
APPL NUMBER: 07-50016992 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D  
IS 1/4 MILE ON LEFT LOT 30 JB  
\*\*\*\*\*PREMISE NUMBER 30626912\*\*\*\*\*  
-----

STRUCTURE: 000 000 40X80 3BDR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/21/08	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001566380
	2/21/08	AP	
B103 01	3/19/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001579440
	3/19/08	AP	
A814 01	3/19/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001579424
	3/19/08	AP	158 BRENDAMOORE CT LOT 30
B105 01	4/18/08	TI	R*OPEN FLOOR VRU #: 001595644

4-18-08 APBS

----- COMMENTS AND NOTES -----

-----  
ADDRESS . : 158 BENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : PHONE :  
OWNER . . : ATKINS PLACE LLC #30 PHONE :  
PARCEL . . : 08-0653- - -0030- -30-  
APPL NUMBER: 07-50016992 CP NEW RESIDENTIAL (SFD)  
-----

DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D  
IS 1/4 MILE ON LEFT LOT 30 JB  
\*\*\*\*\*PREMISE NUMBER 30626912\*\*\*\*\*  
-----

STRUCTURE: 000 000 40X80 3BDR  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/21/08 2/21/08	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001566380
B103 01	3/19/08 3/19/08	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001579440
A814 01	3/19/08 3/19/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001579424 158 BENDAMOORE CT LOT 30
B105 01	4/18/08 4/18/08	BS AP	R*OPEN FLOOR VRU #: 001595644
R425 02	5/16/08 <u>5.16.08</u>	TI <u>DAB</u>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001610682

----- COMMENTS AND NOTES -----

ADDRESS : 158 BRENDAMOORE CT  
CONTRACTOR :  
OWNER : ATKINS PLACE LLC #30  
PARCEL : 08-0653- - -0030- -30-  
APPL NUMBER: 07-50016992 CP NEW RESIDENTIAL (SFD)

SUBDIV: DEXTERFIELD  
PHONE :  
PHONE :

DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D  
IS 1/4 MILE ON LEFT LOT 30 JB  
\*\*\*\*\*PREMISE NUMBER 30626912\*\*\*\*\*

STRUCTURE: 000 000 40X80 3BDR  
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/21/08	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001566380
	2/21/08	AP	
B103 01	3/19/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001579440
	3/19/08	AP	
A814 01	3/19/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001579424
	3/19/08	AP	✓ 158 BRENDAMOORE CT LOT 30
B105 01	4/18/08	BS	R*OPEN FLOOR VRU #: 001595644
	4/18/08	AP	
R425 02	5/16/08	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001610682
	5/16/08	DA	1. Nail joints in OSB at blocking. 2. Cannot strip corners with OSB, must tie back 1 stud. 3. Gas pressure leaked down. 4. Rodent proof tubs/showers with sheet metal and firecaulk. ok to insulate DO NOT SIDE
R425 01	5/19/08	TI	FOUR TRADE ROUGH IN VRU #: 001610666
	5/15/08	CA	
I129 01	5/21/08	BS	R*INSULATION INSPECTION VRU #: 001612525
	5/21/08	AP	
R425 03	5/21/08	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001612753
	5/21/08	AP	
H824 01	6/20/08	BM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001630540
	6/20/08	AP	
R429 01	8/28/08	TI	FOUR TRADE FINAL VRU #: 001668912

8.28.08 APBS

COMMENTS AND NOTES

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Owner: Raynor Builders

911 Address: 158 Broadmoor Ct

FV

State: NC Zip Code: 27526

Date: 8-28-08

Brad Smith

Building Official

PERMIT NUMBERS

Building Permit No.: \_\_\_\_\_

Electrical Permit No.: \_\_\_\_\_

Insulation Permit No.: \_\_\_\_\_

Plumbing Permit No.: \_\_\_\_\_

Mech. Permit No.: 075-16992

MFG. Home: \_\_\_\_\_