

-----  
ADDRESS . : 179 HIGH STANDARD LN  
CONTRACTOR : BRADLEY BUILT INC  
OWNER . . : SHC HOLDINGS INC #43  
PARCEL . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS  
-----

SUBDIV: HUNTERS POINT 45 LOTS  
PHONE : (919) 639-2073  
PHONE : (919) 639-2073

-----  
**STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK**  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 <i>[Signature]</i>	TI <i>[Signature]</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955

-----  
COMMENTS AND NOTES  
-----

-----  
ADDRESS . . : 179 HIGH STANDARD LN  
CONTRACTOR : BRADLEY BUILT INC  
OWNER . . . : SHC HOLDINGS INC #43  
PARCEL . . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS  
-----

SUBDIV: HUNTERS POINT 45 LOTS  
PHONE : (919) 639-2073  
PHONE : (919) 639-2073

**STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW  
-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 <u>7/5/07</u>	TI <u>AP VI</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940

----- COMMENTS AND NOTES -----

ADDRESS : 179 HIGH STANDARD LN  
CONTRACTOR : BRADLEY BUILT INC  
OWNER : SHC HOLDINGS INC #43  
PARCEL : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS

SUBDIV: HUNTERS POINT 45 LOTS  
PHONE : (919) 639-2073  
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848

*AP-MR*

COMMENTS AND NOTES

*No - Temp pole insp.  
wres too small*

ADDRESS : 179 HIGH STANDARD LN  
CONTRACTOR : BRADLEY BUILT INC  
OWNER : SHC HOLDINGS INC #43  
PARCEL : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)

SUBDIV: HUNTERS POINT 45 LOTS  
PHONE : (919) 639-2073  
PHONE : (919) 639-2073

DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 179 High Standard Ln Lot 43
B105 01	7/24/07 <u>3-24</u>	TI <u>AP</u>	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208

COMMENTS AND NOTES

-----  
ADDRESS . : 179 HIGH STANDARD LN SUBDIV: HUNTERS POINT 45 LOTS  
CONTRACTOR : BRADLEY BUILT INC PHONE : (919) 639-2073  
OWNER . . : SHC HOLDINGS INC #43 PHONE : (919) 639-2073  
PARCEL . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS  
-----

**STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW  
-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 179 High Standard Ln Lot 43
B105 01	7/24/07 7/24/07	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
R425 01	8/27/07 <u>8-27</u>	TI <u>DA</u>	FOUR TRADE ROUGH IN VRU #: 001474378

-----  
COMMENTS AND NOTES  
-----

ADDRESS . . : 179 HIGH STANDARD LN  
 CONTRACTOR : BRADLEY BUILT INC  
 OWNER . . . : SHC HOLDINGS INC #43  
 PARCEL . . . : 07-0691- - -0023- -42-  
 APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : HUNTERS POINT #43  
 27 TO COATS LEFT ON 55 TOWARDS ANGIER  
 RT ON SILAS HAYES RD S/D ON RT. JDAVIS

SUBDIV: HUNTERS POINT 45 LOTS  
 PHONE : (919) 639-2073  
 PHONE : (919) 639-2073

**STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . : 3.00  
 SEPTIC - EXISTING? . . . . : NEW  
 PROPOSED USE . . . . . : SFD

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955
	7/03/07	DP	Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
	7/05/07	AP	
B103 01	7/16/07	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
	7/16/07	AP	
A814 01	7/18/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141
	7/24/07	AP	179 High Standard Ln Lot 43
B105 01	7/24/07	KS	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
	7/24/07	AP	
R425 01	8/27/07	KS	FOUR TRADE ROUGH IN VRU #: 001474378
	8/27/07	DA	1. Fire block at floor wall intersection on rear of garage wall. Stud bay cannot be open to floor system. 2. Plywood inside of garage wing walls 3. Nail hurricane ties on front of living room wall. 4. All wire and plubing passing thru top and bottom plate shall be fire caulked. 5. Install fire place Do not insulate.
R425 02	9/04/07	TI	FOUR TRADE ROUGH IN VRU #: 001478379
	<u>9/4/07</u>	<u>AP DT</u>	

COMMENTS AND NOTES

ADDRESS . : 179 HIGH STANDARD LN  
 CONTRACTOR : BRADLEY BUILT INC  
 OWNER . . : SHC HOLDINGS INC #43  
 PARCEL . . : 07-0691- - -0023- -42-  
 APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : HUNTERS POINT #43  
 27 TO COATS LEFT ON 55 TOWARDS ANGIER  
 RT ON SILAS HAYES RD S/D ON RT. JDAVIS

SUBDIV: HUNTERS POINT 45 LOTS  
 PHONE : (919) 639-2073  
 PHONE : (919) 639-2073

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
 FLOOD ZONE . . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 179 High Standard Ln Lot 43
B105 01	7/24/07 7/24/07	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
R425 01	8/27/07 8/27/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001474378 1. Fire block at floor wall intersection on rear of garage wall. Stud bay cannot be open to floor system. 2. Plywood inside of garage wing walls 3. Nail hurricane ties on front of living room wall. 4. All wire and plubing passing thru top and bottom plate shall be fire caulked. 5. Install fire place Do not insulate.
R425 02	9/04/07 9/04/07	DT AP	FOUR TRADE ROUGH IN VRU #: 001478379
I129 01	9/10/07 <u>9-10</u>	TI <u>AP</u>	R*INSULATION INSPECTION VRU #: 001482066 <u>KS</u>

COMMENTS AND NOTES

ADDRESS . : 179 HIGH STANDARD LN  
CONTRACTOR : BRADLEY BUILT INC  
OWNER . . : SHC HOLDINGS INC #43  
PARCEL . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS

SUBDIV: HUNTERS POINT 45 LOTS  
PHONE : (919) 639-2073  
PHONE : (919) 639-2073

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 179 High Standard Ln Lot 43
B105 01	7/24/07 7/24/07	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
R425 01	8/27/07 8/27/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001474378 1. Fire block at floor wall intersection on rear of garage wall. Stud bay cannot be open to floor system. 2. Plywood inside of garage wing walls 3. Nail hurricane ties on front of living room wall. 4. All wire and plubing passing thru top and bottom plate shall be fire caulked. 5. Install fire place Do not insulate.
R425 02	9/04/07 9/04/07	DT AP	FOUR TRADE ROUGH IN VRU #: 001478379
I129 01	9/10/07 9/10/07	KS AP	R*INSULATION INSPECTION VRU #: 001482066
H824 01	10/23/07 10/23/07	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001509595
R429 01	12/06/07 <u>12-06</u>	TI <u>DP</u>	FOUR TRADE FINAL VRU #: 001530583

----- COMMENTS AND NOTES -----



ADDRESS . : 179 HIGH STANDARD LN SUBDIV: HUNTERS POINT 45 LOTS  
CONTRACTOR : BRADLEY BUILT INC PHONE : (919) 639-2073  
OWNER . . : SHC HOLDINGS INC #43 PHONE : (919) 639-2073  
PARCEL . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 ✓179 High Standard Ln Lot 43
B105 01	7/24/07 7/24/07	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
R425 01	8/27/07 8/27/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001474378 1. Fire block at floor wall intersection on rear of garage wall. Stud bay cannot be open to floor system. 2. Plywood inside of garage wing walls 3. Nail hurricane ties on front of living room wall. 4. All wire and plubing passing thru top and bottom plate shall be fire caulked. 5. Install fire place Do not insulate.
R425 02	9/04/07 9/04/07	DT AP	FOUR TRADE ROUGH IN VRU #: 001478379
I129 01	9/10/07 9/10/07	KS AP	R*INSULATION INSPECTION VRU #: 001482066
H824 01	10/23/07 10/23/07	JM AP	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001509595
R429 01	12/06/07 12/06/07	KS DP	FOUR TRADE FINAL VRU #: 001530583 1. Need steps in garage 2. Put dishwasher feeder in box with wire nuts. 3. 20 amp breaker for a/c unit wire not tightened to lug 4. Need wire nuts and cover on jbox in crawl space. 5. Bond gas line
R429 02	12/12/07 <u>12-12</u>	TI <u>DP</u>	FOUR TRADE FINAL VRU #: 001533884

COMMENTS AND NOTES

09465140

**Violation Notice**  
**Do Not Remove**

**Harnett County Inspection Department**  
**102 East Front St P.O. Box 65**  
**Lillington, NC 27546**  
**Phone (910) 893-4876 Fax (910) 893-2793**

07-50017009

1. Need steps to garage door.
2. Put dishwasher feeder in box with wire nuts.
3. 20 amp breaker for A/C unit wire not tightened to breaker lug
4. Need wire nuts and cover on J-box in crawl space.
5. Gas line not bonded

Code Enforcement Official

Signature Ken Slattum 910-984-4766 \_\_\_\_\_

-----  
ADDRESS . : 179 HIGH STANDARD LN SUBDIV: HUNTERS POINT 45 LOTS  
CONTRACTOR : BRADLEY BUILT INC PHONE : (919) 639-2073  
OWNER . . : SHC HOLDINGS INC #43 PHONE : (919) 639-2073  
PARCEL . . : 07-0691- - -0023- -42-  
APPL NUMBER: 07-50017009 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : HUNTERS POINT #43  
27 TO COATS LEFT ON 55 TOWARDS ANGIER  
RT ON SILAS HAYES RD S/D ON RT. JDAVIS  
\*\*PREMISE ##09465140\*\*  
-----

STRUCTURE: 000 000 40X50 3BR W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07 7/03/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001439955 Beam footers not dug to plan. See engineered plan. \$50 re-inspection fee.
B101 02	7/05/07 7/05/07	DT AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440940
B103 01	7/16/07 7/16/07	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001446848
A814 01	7/18/07 7/24/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001448141 179 High Standard Ln Lot 43
B105 01	7/24/07 7/24/07	KS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 001453208
R425 01	8/27/07 8/27/07	KS DA	FOUR TRADE ROUGH IN VRU #: 001474378 1. Fire block at floor wall intersection on rear of garage wall. Stud bay cannot be open to floor system. 2. Plywood inside of garage wing walls 3. Nail hurricane ties on front of living room wall. 4. All wire and plubing passing thru top and bottom plate shall be fire caulked. 5. Install fire place Do not insulate.
R425 02	9/04/07 9/04/07	DT AP	FOUR TRADE ROUGH IN VRU #: 001478379
I129 01	9/10/07 9/10/07	KS AP	R*INSULATION INSPECTION VRU #: 001482066
H824 01	10/23/07 10/23/07	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001509595
R429 01	12/06/07 12/06/07	KS DP	FOUR TRADE FINAL VRU #: 001530583 1. Need steps in garage 2. Put dishwasher feeder in box with wire nuts. 3. 20 amp breaker for a/c unit wire not tightened to lug 4. Need wire nuts and cover on jbox in crawl space. 5. Bond gas line
R429 02	12/12/07 12/12/07	KS DP	FOUR TRADE FINAL VRU #: 001533884 1. House locked. Tried all three doors. 2. 20 amp breaker not wired. Previous violation. 3. Bathroom vent hanging out soffet.
R429 03	12/14/07 <u>12-14</u>	TI <u>AP</u>	FOUR TRADE FINAL VRU #: 001535137

----- COMMENTS AND NOTES -----

**Violation Notice**  
**Do Not Remove**

**Harnett County Inspection Department**  
**102 East Front St P.O. Box 65**  
**Lillington, NC 27546**  
**Phone (910) 893-4876 Fax (910) 893-2793**

07-50017009

1. House locked. Tried all three doors.
2. 20 amp a/c breaker not wired. Previous violation.
3. Bathroom vent hanging out from soffet.
4. \$50.00 re-inspection fee

Code Enforcement Official

Signature Ken Slattum 910-984-4766 \_\_\_\_\_

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential Conditional Use Permit No.: \_\_\_\_\_  
Type of Construction: V Building Permit No.: \_\_\_\_\_  
Owner of Building: Bradley Buell Electrical Permit No.: \_\_\_\_\_  
Building Address: 179 High Standard Insulation Permit No.: \_\_\_\_\_  
Zoning District: \_\_\_\_\_ Plumbing Permit No.: \_\_\_\_\_  
Zoning Permit No.: \_\_\_\_\_ Mech. Permit No.: \_\_\_\_\_  
Date: 12-14-07 Envir. C.O. No.: 07-001700a  
Ken Statum Building Official \_\_\_\_\_ Zoning Official \_\_\_\_\_