

-----

ADDRESS . : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER . . : DIVERSIFIED CONTRACTING INC#63  
 PARCEL . . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD

SUBDIV: COKESBURY PARK  
 PHONE : (919) 460-4490  
 PHONE : (919) 460-4490

-----  
**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . . : FLOOD ZONE X

-----  
**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07 <u>5-2-07</u>	TI <u>ABS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090

----- COMMENTS AND NOTES -----

ADDRESS . : 757 COKESBURY PARK LN  
CONTRACTOR : DIVERSIFIED CONTRACTING  
OWNER . . : DIVERSIFIED CONTRACTING INC#63  
PARCEL . . : 05-0635- - -0124- -25-  
APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : COKESBURY PARK #63 PH3  
401N LEFT ON MARSHALL RAWLS RD TO PINEY  
GROVE WILBON RD LEFT ON 42 LEFT AT  
COKESBURY RD RT ON COKESBURY PARK LN.JD

SUBDIV: COKESBURY PARK  
PHONE : (919) 460-4490  
PHONE : (919) 460-4490

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . . : FLOOD ZONE X

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	<u>6-4-07</u>	<u>APBS</u>	
B113 02	6/04/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	<u>6/4/07</u>	<u>IV</u>	

----- COMMENTS AND NOTES -----

ADDRESS . : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER . . : DIVERSIFIED CONTRACTING INC#63  
 PARCEL . . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD

SUBDIV: COKESBURY PARK  
 PHONE : (919) 460-4490  
 PHONE : (919) 460-4490

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . : 3.00  
 SEPTIC - EXISTING? . . . . : NEW  
 PROPOSED USE . . . . . : SFD

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	TI	R*OPEN FLOOR VRU #: 001423292
	<u>6.6.07</u>	<u>DABS</u>	
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	

COMMENTS AND NOTES

-----  
 ADDRESS . : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER . . : DIVERSIFIED CONTRACTING INC#63  
 PARCEL . . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD  
 -----

STRUCTURE: 000 000 36X45 3BR W/GARAGE  
 FLOOD ZONE . . . . : FLOOD ZONE X  
 -----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	TI	R*OPEN FLOOR VRU #: 001425164

6/8/07 ABS

----- COMMENTS AND NOTES -----

-----  
 ADDRESS . : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
 CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
 OWNER . . : DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
 PARCEL . . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD  
 -----

STRUCTURE: 000 000 36X45 3BR W/GARAGE

FLOOD ZONE . . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	TI	FOUR TRADE ROUGH IN VRU #: 001454206

7-27-07 DABK

----- COMMENTS AND NOTES -----

ADDRESS : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER : DIVERSIFIED CONTRACTING INC#63  
 PARCEL : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)

SUBDIV: COKESBURY PARK  
 PHONE : (919) 460-4490  
 PHONE : (919) 460-4490

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	TI	R*INSULATION INSPECTION VRU #: 001461730
	<u>8-8-07</u>	<u>DABS</u>	
R125 01	8/08/07	TI	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	<u>8/08/07</u>	<u>IVR</u>	

COMMENTS AND NOTES

*No Letter*

Diversified  
Contracting  
Incorporated

\* FAX \*

\* COVER \*

04 500 17090

COVER

SHEET

TO: HARNETT Co. WSP. DEPT

DATE: 8.10.07

Attn: BRAD SUTTON

Fax #: 910.814.8277

From: RAY FEGER

Subject: \_\_\_\_\_

Pages: 3, (including this cover sheet)

ORIGINALS MAILED  YES  NO

\*\*\*\*\*

COMMENTS

FOLLOWING ENG. LTR. PER YOUR REQUEST.

**Violation Notice  
Do Not Remove**

**Harnett County Inspection Department  
102 East Front St P.O. Box 65  
Lillington, NC 27546  
Phone (910) 893-4876 Fax (910) 893-2793**


App # 07-50017090 Diversified contracting 757 Cokesbury park

Need engineers letter on cantilever. Email to [bsutton@harnett.org](mailto:bsutton@harnett.org) or fax to 910-814-8277. DO NOT SHEETROCK.

Code Enforcement Official

Signature Brad Sutton 8-8-07





**SAMIR W. BAHHO P.E.**  
**CIVIL AND STRUCTURAL ENGINEERING**

Date: August 9, 2007

Diversified Contracting, Inc.  
Raymond G, Feger  
110 Woodwinds Industrial Ct.  
Cary, North Carolina 27511

Reference: The Camden-Lot # 63, Permit 0750017090-  
Cantilever certification letter

Structural Calculation has been conducted to the section of cantilever as constructed on the house subject of permit # 0750017090, Lot # 63. I hereby certify cantilever as constructed meets load requirement of North Carolina Building Code. My professional seal is affixed below for certification.

For any additional questions call me or email me. My telephone number is 919-621-0628. My email address is bahhos@bellsouth.net.

Sincerely,

*Samir W. Bahho*  
Samir W. Bahho, P.E.

Cc: File (1)



8/9/07

*Samir W. Bahho*

ADDRESS : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER : DIVERSIFIED CONTRACTING INC#63  
 PARCEL : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD

SUBDIV: COKESBURY PARK  
 PHONE : (919) 460-4490  
 PHONE : (919) 460-4490

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . . : FLOOD ZONE X

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	BS	R*INSULATION INSPECTION VRU #: 001461730
	8/08/07	DA	
R125 01	8/08/07	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	8/08/07	DA	no engineers report at job
P307 01	10/05/07	TI	R*PLUMB WATER CONNECTION VRU #: 001499177

10-5-07 APBS

-----  
 ADDRESS . : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
 CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
 OWNER . : DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
 PARCEL . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD  
 -----

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . : FLOOD ZONE X  
 -----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick upvent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	BS	R*INSULATION INSPECTION VRU #: 001461730
	8/08/07	DA	
R125 01	8/08/07	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	8/08/07	DA	no engineers report at job
P307 01	10/05/07	BS	R*PLUMB WATER CONNECTION VRU #: 001499177
	10/05/07	AP	
B101 02	10/24/07	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001508555
	10/24/07	CA	WILL BE FOR THE PIER FOOTING FOR THE DECK.
B101 03	10/30/07	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001511989

-----  
ADDRESS . : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
OWNER . : DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
PARCEL . . : 05-0635- - -0124- -25-  
APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	<u>10-30-07</u>	<u>APBS</u>	WILL BE FOR THE DECKS.

----- COMMENTS AND NOTES -----

ADDRESS : 757 COKESBURY PARK LN  
 CONTRACTOR : DIVERSIFIED CONTRACTING  
 OWNER : DIVERSIFIED CONTRACTING INC#63  
 PARCEL : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)

SUBDIV: COKESBURY PARK  
 PHONE : (919) 460-4490  
 PHONE : (919) 460-4490

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	BS	R*INSULATION INSPECTION VRU #: 001461730
	8/08/07	DA	
R125 01	8/08/07	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	8/08/07	DA	no engineers report at job
P307 01	10/05/07	BS	R*PLUMB WATER CONNECTION VRU #: 001499177
	10/05/07	AP	
B101 02	10/24/07	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001508555
	10/24/07	CA	WILL BE FOR THE PIER FOOTING FOR THE DECK.
B101 03	10/30/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001511989
	10/30/07	AP	WILL BE FOR THE DECKS.
H824 01	12/10/07	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533777
	12/10/07	AP	
M305 01	12/18/07	TI	R*PLUMB SEWER CONNECTION VRU #: 001536796

12-18-07 APBS

ADDRESS : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
 CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
 OWNER : DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
 PARCEL : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . : FLOOD ZONE X

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	BS	R*INSULATION INSPECTION VRU #: 001461730
	8/08/07	DA	
R125 01	8/08/07	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	8/08/07	DA	no engineers report at job
P307 01	10/05/07	BS	R*PLUMB WATER CONNECTION VRU #: 001499177
	10/05/07	AP	
B101 02	10/24/07	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001508555
	10/24/07	CA	WILL BE FOR THE PIER FOOTING FOR THE DECK.
B101 03	10/30/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001511989

-----  
ADDRESS . : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
OWNER . . \ DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
PARCEL . . : 05-0635- - -0124- -25-  
APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	10/30/07	AP	WILL BE FOR THE DECKS.
H824 01	12/10/07	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533777
	12/10/07	AP	
M305 01	12/18/07	BS	R*PLUMB SEWER CONNECTION VRU #: 001536796
	12/18/07	AP	
R429 01	2/11/08	TI	FOUR TRADE FINAL VRU #: 001560440

*2-11-08* *DAB*

----- COMMENTS AND NOTES -----  
-----

ADDRESS . : 757 COKESBURY PARK LN SUBDIV: COKESBURY PARK  
 CONTRACTOR : DIVERSIFIED CONTRACTING PHONE : (919) 460-4490  
 OWNER . . . : DIVERSIFIED CONTRACTING INC#63 PHONE : (919) 460-4490  
 PARCEL . . : 05-0635- - -0124- -25-  
 APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : COKESBURY PARK #63 PH3  
 401N LEFT ON MARSHALL RAWLS RD TO PINEY  
 GROVE WILBON RD LEFT ON 42 LEFT AT  
 COKESBURY RD RT ON COKESBURY PARK LN.JD

**STRUCTURE: 000 000 36X45 3BR W/GARAGE**

FLOOD ZONE . . . : FLOOD ZONE X

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/02/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001401090
	5/02/07	AP	
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415506
	5/31/07	AP	✓757 COKESBURY PARK LN
B103 01	6/01/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001418607
	5/31/07	CA	
B113 01	6/01/07	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001418615
	5/31/07	CA	
B103 02	6/04/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001420694
	6/04/07	AP	
B113 02	6/04/07	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001420702
	6/04/07	AP	
B105 03	6/06/07	BS	R*OPEN FLOOR VRU #: 001423292
	6/06/07	DA	At cantilevers, where joists extend over vent openings, either brick up the vents fully and move, or install 3x5 painted angle steel over vent opening, angle must extend 3 inches either side of opening. DO NOT COVER, CALL TO RESCHEDULE
B105 01	6/06/07	TI	R*OPEN FLOOR VRU #: 001423169
	6/04/07	CA	
B105 02	6/07/07	TI	R*OPEN FLOOR VRU #: 001423227
	6/04/07	CA	
B105 04	6/08/07	BS	R*OPEN FLOOR VRU #: 001425164
	6/08/07	AP	Brick up vent hole full thickness of wall below. Ok to cover, will check at rough ins
R425 01	7/25/07	TI	FOUR TRADE ROUGH IN VRU #: 001452515
	7/24/07	CA	
R425 02	7/26/07	TI	FOUR TRADE ROUGH IN VRU #: 001453356
	7/25/07	CA	
R425 03	7/27/07	BS	FOUR TRADE ROUGH IN VRU #: 001454206
	7/27/07	DA	1. Bolt LVL in garage 1/2 thru bolts 2' oc staggered. 2. flash front and rear porches 3. Need engineering on second floor cantilever.
I129 01	8/03/07	TI	R*INSULATION INSPECTION VRU #: 001459544
	8/02/07	CA	
I129 02	8/08/07	BS	R*INSULATION INSPECTION VRU #: 001461730
	8/08/07	DA	
R125 01	8/08/07	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 001463827
	8/08/07	DA	no engineers report at job
P307 01	10/05/07	BS	R*PLUMB WATER CONNECTION VRU #: 001499177
	10/05/07	AP	
B101 02	10/24/07	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001508555
	10/24/07	CA	WILL BE FOR THE PIER FOOTING FOR THE DECK.
B101 03	10/30/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001511989



ADDRESS : 757 COKESBURY PARK LN  
CONTRACTOR : DIVERSIFIED CONTRACTING  
OWNER : DIVERSIFIED CONTRACTING INC#63  
PARCEL : 05-0635- - -0124- -25-  
APPL NUMBER: 07-50017090 CP NEW RESIDENTIAL (SFD)

SUBDIV: COKESBURY PARK  
PHONE : (919) 460-4490  
PHONE : (919) 460-4490

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	10/30/07	AP	WILL BE FOR THE DECKS.
H824 01	12/10/07	BM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533777
	12/10/07	AP	
M305 01	12/18/07	BS	R*PLUMB SEWER CONNECTION VRU #: 001536796
	12/18/07	AP	
R429 01	2/11/08	BS	FOUR TRADE FINAL VRU #: 001560440
	2/11/08	DA	1. Need plastic under house. 2. Strap ductwork under house laying on the ground 3. Washer Dryer closet needs 100 sq inches free air space. 4. Adjust door to unfinished space so that it contacts the weatherstrip fully at all points
R429 02	3/03/08 <u>3-3-08</u>	TI <u>ARBS</u>	FOUR TRADE FINAL VRU #: 001569748 House is locked, please call my cell number 868.1968 and let me know if inspection is AM or PM and I'll gladly meet inspector and unlock. Thank you, Ray Feger.

----- COMMENTS AND NOTES -----

SAM

~~NSM~~

~~ARBS~~

< 17151126

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Type of Construction: V

Owner of Building: Disvised Contracting

Building Address: 757 Cokerbury Park Ln

Zoning District: \_\_\_\_\_

Zoning Permit No.: N/A

Date: 3-3-18

Burd Sutter

Building Official

Conditional Use Permit No.: \_\_\_\_\_

Building Permit No.: \_\_\_\_\_

Electrical Permit No.: \_\_\_\_\_

Insulation Permit No.: \_\_\_\_\_

Plumbing Permit No.: 0-5-17-190

Mech. Permit No.: \_\_\_\_\_

Envir. C.O. No.: \_\_\_\_\_

Zoning Official