

-----  
ADDRESS . : 15 BENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
OWNER . . : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
PARCEL . . : 08-0653- - -0030- -59-  
APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
RD LEFT INTO S/D RT ON BENDAMOORE LOT  
ON CORNER OF ALVIS, DRIVEWAY OFF  
BENDAMOORE.JD  
-----

STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07 <u>9-7-07</u>	TI <u>APBS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257

----- COMMENTS AND NOTES -----  
-----

-----  
ADDRESS . : 15 BENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
OWNER . . : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
PARCEL . . : 08-0653- - -0030- -59-  
APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
RD LEFT INTO S/D RT ON BENDAMOORE LOT  
ON CORNER OF ALVIS, DRIVEWAY OFF  
BENDAMOORE.JD  
-----

STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257
	9/07/07	AP	
B103 01	9/13/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001483834
	<u>9.13.07</u>	<u>ABS</u>	

----- COMMENTS AND NOTES -----  
-----

-----  
ADDRESS . : 15 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
OWNER . . : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
PARCEL . . : 08-0653- - -0030- -59-  
APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
RD LEFT INTO S/D RT ON BRENDAMOORE LOT  
ON CORNER OF ALVIS, DRIVEWAY OFF  
BRENDAMOORE.JD  
-----

STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07 9/07/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257
B103 01	9/13/07 9/13/07	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001483834
A814 01	9/17/07 9/12/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001483825 15 BRENDAMOORE CT
B105 01	9/25/07 <u>9/25/07</u>	TI <u>APRS</u>	R*OPEN FLOOR VRU #: 001492281

----- COMMENTS AND NOTES -----

23091

-----  
ADDRESS . : 15 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
OWNER . . : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
PARCEL . . : 08-0653- - -0030- -59-  
APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
RD LEFT INTO S/D RT ON BRENDAMOORE LOT  
ON CORNER OF ALVIS, DRIVEWAY OFF  
BRENDAMOORE.JD  
-----

STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK  
FLOOD ZONE . . . . : FLOOD ZONE X  
-----

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257
	9/07/07	AP	
B103 01	9/13/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001483834
	9/13/07	AP	
A814 01	9/17/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001483825
	9/12/07	AP	15 BRENDAMOORE CT
B105 01	9/25/07	BS	R*OPEN FLOOR VRU #: 001492281
	9/25/07	AP	
R425 01	10/11/07	TI	FOUR TRADE ROUGH IN VRU #: 001501574

10-11-07 DABS

----- COMMENTS AND NOTES -----

ADDRESS : 15 BENDAMOORE CT SUBDIV: DEXTERFIELD  
 CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
 OWNER : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
 PARCEL : 08-0653- - -0030- -59-  
 APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
 RD LEFT INTO S/D RT ON BENDAMOORE LOT  
 ON CORNER OF ALVIS, DRIVEWAY OFF  
 BENDAMOORE.JD

**STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257
	9/07/07	AP	
B103 01	9/13/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001483834
	9/13/07	AP	
A814 01	9/17/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001483825
	9/12/07	AP	15 BENDAMOORE CT
B105 01	9/25/07	BS	R*OPEN FLOOR VRU #: 001492281
	9/25/07	AP	
R425 01	10/11/07	BS	FOUR TRADE ROUGH IN VRU #: 001501574
	10/11/07	DA	1. Missing double floor joist over front bedroom and hangers at stairs (see plan) Do not notch joist for wiring; pull out wiring, add joist and drill holes. ok to side/insulate
I129 01	10/15/07	TI	R*INSULATION INSPECTION VRU #: 001503661
	10/15/07	CA	
R425 02	10/15/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001504505
	10/15/07	CA	
I129 02	10/16/07	TI	R*INSULATION INSPECTION VRU #: 001504786
	10-16	AP	
R425 03	10/16/07	TI	FOUR TRADE ROUGH IN VRU #: 001504778
	10-16	AP	

COMMENTS AND NOTES

ADDRESS : 15 BRENDAMOORE CT SUBDIV: DEXTERFIELD  
CONTRACTOR : STEPHENSON BUILDERS, INC. PHONE : (919) 427-8654  
OWNER : STEPHENSON BUILDERS INC #59 PHONE : (910) 427-8654  
PARCEL : 08-0653- - -0030- -59-  
APPL NUMBER: 07-50018309 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : DEXTERFIELD #59-401N LEFT ON CHALYBEATE  
RD LEFT INTO S/D RT ON BRENDAMOORE LOT  
ON CORNER OF ALVIS, DRIVEWAY OFF  
BRENDAMOORE.JD

STRUCTURE: 000 000 64X58 3BR CRAWL W/GARAGE & DECK  
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/07/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001481257
	9/07/07	AP	
B103 01	9/13/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001483834
	9/13/07	AP	
A814 01	9/17/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001483825
	9/12/07	AP	15 BRENDAMOORE CT
B105 01	9/25/07	BS	R*OPEN FLOOR VRU #: 001492281
	9/25/07	AP	
R425 01	10/11/07	BS	FOUR TRADE ROUGH IN VRU #: 001501574
	10/11/07	DA	1. Missing double floor joist over front bedroom and hangers at stairs (see plan) Do not notch joist for wiring; pull out wiring, add joist and drill holes. ok to side/insulate
I129 01	10/15/07	TI	R*INSULATION INSPECTION VRU #: 001503661
	10/15/07	CA	
R425 02	10/15/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001504505
	10/15/07	CA	
I129 02	10/16/07	KS	R*INSULATION INSPECTION VRU #: 001504786
	10/16/07	AP	
R425 03	10/16/07	KS	FOUR TRADE ROUGH IN VRU #: 001504778
	10/16/07	AP	
H824 01	11/19/07	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001523570
	11/19/07	AP	
R429 01	12/03/07	TI	FOUR TRADE FINAL VRU #: 001527351

12-3-07 APBS

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Conditional Use Permit No.: \_\_\_\_\_

Type of Construction: II

Building Permit No.: \_\_\_\_\_

Owner of Building: Stephenson Bldgs

Electrical Permit No.: \_\_\_\_\_

Building Address: 15 Brandamouct

Insulation Permit No.: \_\_\_\_\_

Zoning District: \_\_\_\_\_

Plumbing Permit No.: \_\_\_\_\_

Zoning Permit No.: N/A

Mech. Permit No.: \_\_\_\_\_

Date: 12-03-07

Envir. C.O. No.: 075-18309

Brad Sitter

Building Official

\_\_\_\_\_

Zoning Official