

August 8, 2008

Stancil Builders Inc
466 Stancil Rd.
Angier, NC 27501

Re: Status of Improvement Permit Application #08-5-19885RR


To Whom It May Concern,

On August 6, 2008, an attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Property lines/corners not marked or labeled (*\$25.00 fee incurred*)
- 2. House corners not marked or labeled (*\$25.00 fee incurred*)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Property needs brush or vegetation removed
- 5. Backhoe pits required
- 6. **Other – Plot plan must match proposal from your consultant. Make changes to plot plan and submit new plot plan to Central Permitting.**

Your application will be put on hold until the selected items above have been addressed.
When completed please call 910-893-7527 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Joe West, R. S.
Environmental Health Specialist
Harnett County Department of Public Health

JW/sgs
Copy: Central Permitting

Southeastern Soil & Environmental Associates, Inc.


P.O. Box 9321
Fayetteville, NC 28311
Phone/Fax (910) 822-4540
Email mike@southeasternsoil.com

PATTONS POINT

PHASE 2

LOT 194

Proposed Septic



Jump out

65' from Front Property Line

1" = 60'