

COUNTY OF HARNETT  
Building Inspections Department  
Planning Services

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Allen Custom Construction  
LLC

Address: 145 English Springer Dr.

Permit Numbers

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

08-50020019

Date: 5-10-13

Building Official: Ken Statt

ADDRESS : 145 ENGLISH SPRINGER DR SUBDIV: QUAIL GLEN PH1 32LOTS  
CONTRACTOR : ALLEN CUSTOM CONSTRUCTION LLC PHONE : (910) 814-2721  
OWNER : ALLEN JOSEPH BRETT & SOMMER PHONE : (910) 814-2721  
PARCEL : 11-0662- - -0022- -11-  
APPL NUMBER: 08-50020019 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : TAKE 210 TOWARD ANGIER TURN LEFT ON  
HARNETT CENTRAL RD GO APPROX 1/2 MILE  
AND S/D WILL BE ON YOUR LEFT LOT 8 IS  
ON THE LEFT LOT 8 JB  
T/S: 06/29/2012 02:59 PM VBROWN ----  
PREMIS NUMBER 80235450

STRUCTURE: 000 000 38X50 4BDR W/ GARAGE & DECK CRAWL  
FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 4.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/21/12	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002242415 T/S: 06/21/2012 11:47 AM DETAYLOR -----
B103 01	6/29/12	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002245454 T/S: June 29, 2012 09:34 AM BSUTTON -----
A814 01	7/02/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002246031 145 ENGLISH SPRINGER DR LOT 8 ANGIER 27501 T/S: 06/29/2012 03:28 PM TWARD -----
B105 01	7/05/12	BS	R*OPEN FLOOR VRU #: 002247438 T/S: July 05, 2012 11:11 AM BSUTTON -----
R427 01	8/03/12	KS	FOUR TRADE ROUGH IN >2500 VRU #: 002260404 T/S: 08/03/2012 12:26 PM KSLATTUM ----- Need fall protection device on upstairs window. 2. dryer duct exceeds 35 feet in length. OK to side and insulate
I129 01	8/08/12	DT	R*INSULATION INSPECTION VRU #: 002262319 T/S: 08/08/2012 11:34 AM DETAYLOR -----
R427 02	8/08/12	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002262541 T/S: 08/07/2012 02:48 PM DJOHNSON ----- T/S: 08/08/2012 11:34 AM DETAYLOR -----
H824 01	9/25/12	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002286318 T/S: 10/02/2012 03:46 PM SSTEWARD ----- T/S: 10/02/2012 03:46 PM SSTEWARD -----
R429 01	5/09/13	DT	FOUR TRADE FINAL TIME: 17:00 VRU #: 002378958 T/S: 05/07/2013 03:47 PM VBROWN ----- T/S: 05/09/2013 11:20 AM DETAYLOR ----- Missing hand rails for front steps and guard rails for rear porch and steps
R429 02	5/13/13	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002380624

5-13 TI AP